

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-10/12/05	030530646-0001	Southwest Area (street-level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/12/05	030530646-0002	Southeast Area (sidewalk bridge level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/12/05	030530646-0003	Northwest Area (street-level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/12/05	030530646-0004	Firehouse #10 (roof level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/12/05	030530646-0005	North Side Sidewalk Bridge	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/12/05	030530646-0006	90 Trinity Place (roof level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/12/05	030530646-0007	110 Greenwich Street (roof level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/12/05	030530646-0008	Marriott Hotel, 38th Floor (roof level)	10/12/2005	1	2.890	Asbestos	PCME	EMSL	10/13/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/13/05	030530761-0001	Southwest Area (street-level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/13/05	030530761-0002	Southeast Area (sidewalk bridge level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/13/05	030530761-0003	Northwest Area (street-level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/13/05	030530761-0004	Firehouse #10 (roof level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/13/05	030530761-0005	North Side Sidewalk Bridge	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/13/05	030530761-0006	90 Trinity Place (roof level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/13/05	030530761-0007	110 Greenwich Street (roof level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/13/05	030530761-0008	Marriott Hotel, 38th Floor (roof level)	10/13/2005	1	2.890	Asbestos	PCME	EMSL	10/14/2005	< 0.00085	No	No	