

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|--------------------|------------------------------|----------|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Site Specific Trigger Levels | |
| | | | | | | | | | | NA | | | |
| ABESTOS-ST1-10/13/06 | 030633889-0001 | Southwest Area (sidewalk bridge level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST2-10/13/06 | 030633889-0002 | Southeast Area (sidewalk bridge level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST4-10/13/06 | 030633889-0003 | Northwest Area (street-level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST5-10/13/06 | 030633889-0004 | Firehouse #10 (roof level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST10-10/13/06 | 030633889-0005 | North Side Sidewalk Bridge | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST100-10/13/06 | 030633889-0013 | Station 10 Field Duplicate | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST11-10/13/06 | 030633889-0006 | 90 Trinity Place (roof level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST12-10/13/06 | 030633889-0007 | 110 Greenwich Street (roof level) | 10/13/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00081 | No | No | |
| ABESTOS-ST13-10/13/06 | 030633889-0008 | Marriott Hotel, 38th Floor (roof level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST14-10/13/06 | 030633889-0009 | West Face - South end at corner (scaffolding level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST15-10/13/06 | 030633889-0010 | South Face - East end at corner (scaffolding level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST16-10/13/06 | 030633889-0011 | East Face - North end at corner (scaffolding level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ABESTOS-ST17-10/13/06 | 030633889-0012 | North Face - West end at corner (scaffolding level) | 10/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST1-10/14/06 | 030633890-0001 | Southwest Area (sidewalk bridge level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST2-10/14/06 | 030633890-0002 | Southeast Area (sidewalk bridge level) | 10/14/06 | 1 | 3.050 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00081 | No | No | |
| ASBESTOS-ST4-10/14/06 | 030633890-0003 | Northwest Area (street-level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST5-10/14/06 | 030633890-0004 | Firehouse #10 (roof level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST10-10/14/06 | 030633890-0005 | North Side Sidewalk Bridge | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST11-10/14/06 | 030633890-0006 | 90 Trinity Place (roof level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST12-10/14/06 | 030633890-0007 | 110 Greenwich Street (roof level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST13-10/14/06 | 030633890-0008 | Marriott Hotel, 38th Floor (roof level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST14-10/14/06 | 030633890-0009 | West Face - South end at corner (scaffolding level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST15-10/14/06 | 030633890-0010 | South Face - East end at corner (scaffolding level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST16-10/14/06 | 030633890-0011 | East Face - North end at corner (scaffolding level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST17-10/14/06 | 030633890-0012 | North Face - West end at corner (scaffolding level) | 10/14/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST1-10/15/06 | 030633887-0001 | Southwest Area (sidewalk bridge level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST2-10/15/06 | 030633887-0002 | Southeast Area (sidewalk bridge level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST4-10/15/06 | 030633887-0003 | Northwest Area (street-level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST5-10/15/06 | 030633887-0004 | Firehouse #10 (roof level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST10-10/15/06 | 030633887-0005 | North Side Sidewalk Bridge | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST11-10/15/06 | 030633887-0006 | 90 Trinity Place (roof level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST12-10/15/06 | 030633887-0007 | 110 Greenwich Street (roof level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST13-10/15/06 | 030633887-0008 | Marriott Hotel, 38th Floor (roof level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST14-10/15/06 | 030633887-0009 | West Face - South end at corner (scaffolding level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST15-10/15/06 | 030633887-0010 | South Face - East end at corner (scaffolding level) | 10/15/06 | 1 | 3.060 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00081 | No | No | |
| ASBESTOS-ST16-10/15/06 | 030633887-0011 | East Face - North end at corner (scaffolding level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST17-10/15/06 | 030633887-0012 | North Face - West end at corner (scaffolding level) | 10/15/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/16/06 | < 0.00082 | No | No | |
| ASBESTOS-ST1-10/16/06 | 030634025-0001 | Southwest Area (sidewalk bridge level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST2-10/16/06 | 030634025-0002 | Southeast Area (sidewalk bridge level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST4-10/16/06 | 030634025-0003 | Northwest Area (street-level) | 10/16/06 | 1 | 3.280 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00075 | No | No | |
| ASBESTOS-ST5-10/16/06 | 030634025-0004 | Firehouse #10 (roof level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST10-10/16/06 | 030634025-0005 | North Side Sidewalk Bridge | 10/16/06 | 1 | 3.090 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00080 | No | No | |
| ASBESTOS-ST11-10/16/06 | 030634025-0006 | 90 Trinity Place (roof level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST12-10/16/06 | 030634025-0007 | 110 Greenwich Street (roof level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST13-10/16/06 | 030634025-0008 | Marriott Hotel, 38th Floor (roof level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST14-10/16/06 | 030634025-0009 | West Face - South end at corner (scaffolding level) | 10/16/06 | 1 | 3.090 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00080 | No | No | |
| ASBESTOS-ST15-10/16/06 | 030634025-0010 | South Face - East end at corner (scaffolding level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |
| ASBESTOS-ST16-10/16/06 | 030634025-0011 | East Face - North end at corner (scaffolding level) | 10/16/06 | 1 | 2.900 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00085 | No | No | |
| ASBESTOS-ST17-10/16/06 | 030634025-0012 | North Face - West end at corner (scaffolding level) | 10/16/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 10/17/06 | < 0.00082 | No | No | |