

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-10/18/07	030734341-0001	Southwest Area (sidewalk bridge level)	10/18/07	1	3.060	Asbestos	PCME	EMSL	10/19/07	< 0.00081	No	No	
ASBESTOS-ST2-10/18/07	030734341-0002	Southeast Area (sidewalk bridge level)	10/18/07	1	3.000	Asbestos	PCME	EMSL	10/19/07	< 0.00082	No	No	
ASBESTOS-ST4-10/18/07	030734341-0003	Northwest Area (street-level)	10/18/07	1	3.150	Asbestos	PCME	EMSL	10/19/07	< 0.00078	No	No	
ASBESTOS-ST5-10/18/07	030734341-0004	Firehouse #10 (roof level)	10/18/07	1	3.060	Asbestos	PCME	EMSL	10/19/07	< 0.00081	No	No	
ASBESTOS-ST10-10/18/07	030734341-0005	North Side Sidewalk Bridge	10/18/07	1	3.210	Asbestos	PCME	EMSL	10/19/07	< 0.00077	No	No	
ASBESTOS-ST11-10/18/07	030734341-0006	90 Trinity Place (roof level)	10/18/07	1	3.060	Asbestos	PCME	EMSL	10/19/07	< 0.00081	No	No	
ASBESTOS-ST12-10/18/07	030734341-0007	110 Greenwich Street (roof level)	10/18/07	1	3.040	Asbestos	PCME	EMSL	10/19/07	< 0.00081	No	No	
ASBESTOS-ST13-10/18/07	030734341-0008	Marriott Hotel, 38th Floor (roof level)	10/18/07	1	2.960	Asbestos	PCME	EMSL	10/19/07	< 0.00083	No	No	
ASBESTOS-ST14-10/18/07	030734341-0009	West Face - South end at corner (scaffolding level)	10/18/07	1	3.150	Asbestos	PCME	EMSL	10/19/07	< 0.00078	No	No	
ASBESTOS-ST15-10/18/07	030734341-0010	South Face - East end at corner (scaffolding level)	10/18/07	1	3.050	Asbestos	PCME	EMSL	10/19/07	< 0.00081	No	No	
ASBESTOS-ST16-10/18/07	030734341-0011	East Face - North end at corner (scaffolding level)	10/18/07	1	2.960	Asbestos	PCME	EMSL	10/19/07	< 0.00083	No	No	
ASBESTOS-ST17-10/18/07	030734341-0012	North Face - West end at corner (scaffolding level)	10/18/07	1	2.940	Asbestos	PCME	EMSL	10/19/07	< 0.00084	No	No	
ASBESTOS-ST1-10/19/07	030734420-0001	Southwest Area (sidewalk bridge level)	10/19/07	1	3.120	Asbestos	PCME	EMSL	10/20/07	< 0.00079	No	No	
ASBESTOS-ST2-10/19/07	030734420-0002	Southeast Area (sidewalk bridge level)	10/19/07	1	2.950	Asbestos	PCME	EMSL	10/20/07	< 0.00084	No	No	
ASBESTOS-ST4-10/19/07	030734420-0003	Northwest Area (street-level)	10/19/07	1	3.080	Asbestos	PCME	EMSL	10/20/07	< 0.00080	No	No	
ASBESTOS-ST5-10/19/07	030734420-0004	Firehouse #10 (roof level)	10/19/07	1	3.010	Asbestos	PCME	EMSL	10/20/07	< 0.00082	No	No	
ASBESTOS-ST10-10/19/07	030734420-0005	North Side Sidewalk Bridge	10/19/07	1	3.080	Asbestos	PCME	EMSL	10/20/07	< 0.00080	No	No	
ASBESTOS-ST11-10/19/07	030734420-0006	90 Trinity Place (roof level)	10/19/07	1	3.000	Asbestos	PCME	EMSL	10/20/07	< 0.00082	No	No	
ASBESTOS-ST12-10/19/07	030734420-0007	110 Greenwich Street (roof level)	10/19/07	1	3.020	Asbestos	PCME	EMSL	10/20/07	< 0.00082	No	No	
ASBESTOS-ST13-10/19/07	030734420-0008	Marriott Hotel, 38th Floor (roof level)	10/19/07	1	3.040	Asbestos	PCME	EMSL	10/20/07	< 0.00081	No	No	
ASBESTOS-ST15-10/19/07	030734420-0009	South Face - East end at corner (scaffolding level)	10/19/07	1	3.020	Asbestos	PCME	EMSL	10/20/07	< 0.00082	No	No	
ASBESTOS-ST16-10/19/07	030734420-0010	East Face - North end at corner (scaffolding level)	10/19/07	1	3.010	Asbestos	PCME	EMSL	10/20/07	< 0.00082	No	No	

Note:
1. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) on October 19, 2007 were not available for analysis on account of power failure.