

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-10/18/08	030837440-0001	Southwest Area (sidewalk bridge level)	10/18/08	1	2.840	Asbestos	PCME	EMSL	10/22/08	< 0.00087	No	No	
ASBESTOS-ST2-10/18/08	030837440-0002	Southeast Area (sidewalk bridge level)	10/18/08	1	2.920	Asbestos	PCME	EMSL	10/22/08	< 0.00085	No	No	
ASBESTOS-ST4-10/18/08	030837440-0003	Northwest Area (street-level)	10/18/08	1	2.440	Asbestos	PCME	EMSL	10/22/08	< 0.00087	No	No	Note 1
ASBESTOS-ST5-10/18/08	030837440-0004	Firehouse #10 (roof level)	10/18/08	1	3.020	Asbestos	PCME	EMSL	10/22/08	< 0.00082	No	No	
ASBESTOS-ST10-10/18/08	030837440-0005	North Side Sidewalk Bridge	10/18/08	1	2.980	Asbestos	PCME	EMSL	10/22/08	< 0.00083	No	No	
ASBESTOS-ST11-10/18/08	030837440-0006	90 Trinity Place (roof level)	10/18/08	1	3.060	Asbestos	PCME	EMSL	10/22/08	< 0.00081	No	No	
ASBESTOS-ST12-10/18/08	030837440-0007	110 Greenwich Street (roof level)	10/18/08	1	2.970	Asbestos	PCME	EMSL	10/22/08	< 0.00083	No	No	
ASBESTOS-ST13-10/18/08	030837440-0008	Marriott Hotel, 38th Floor (roof level)	10/18/08	1	3.010	Asbestos	PCME	EMSL	10/22/08	< 0.00082	No	No	
ASBESTOS-ST14-10/18/08	030837440-0009	West Face - South end at corner (scaffolding level)	10/18/08	1	3.030	Asbestos	PCME	EMSL	10/22/08	< 0.00081	No	No	
ASBESTOS-ST15-10/18/08	030837440-0010	South Face - East end at corner (scaffolding level)	10/18/08	1	2.980	Asbestos	PCME	EMSL	10/22/08	< 0.00083	No	No	
ASBESTOS-ST16-10/18/08	030837440-0011	East Face - North end at corner (scaffolding level)	10/18/08	1	3.050	Asbestos	PCME	EMSL	10/22/08	< 0.00081	No	No	
ASBESTOS-ST17-10/18/08	030837440-0012	North Face - West end at corner (scaffolding level)	10/18/08	1	3.000	Asbestos	PCME	EMSL	10/22/08	< 0.00082	No	No	
ASBESTOS-ST1-10/19/08	030837169-0001	Southwest Area (sidewalk bridge level)	10/19/08	1	3.070	Asbestos	PCME	EMSL	10/20/08	< 0.00080	No	No	
ASBESTOS-ST2-10/19/08	030837169-0002	Southeast Area (sidewalk bridge level)	10/19/08	1	3.040	Asbestos	PCME	EMSL	10/20/08	< 0.00081	No	No	
ASBESTOS-ST4-10/19/08	030837169-0003	Northwest Area (street-level)	10/19/08	1	3.070	Asbestos	PCME	EMSL	10/20/08	< 0.00080	No	No	
ASBESTOS-ST5-10/19/08	030837169-0004	Firehouse #10 (roof level)	10/19/08	1	3.030	Asbestos	PCME	EMSL	10/20/08	< 0.00081	No	No	
ASBESTOS-ST10-10/19/08	030837169-0005	North Side Sidewalk Bridge	10/19/08	1	3.050	Asbestos	PCME	EMSL	10/20/08	< 0.00081	No	No	
ASBESTOS-ST11-10/19/08	030837169-0006	90 Trinity Place (roof level)	10/19/08	1	3.080	Asbestos	PCME	EMSL	10/20/08	< 0.00080	No	No	
ASBESTOS-ST12-10/19/08	030837169-0007	110 Greenwich Street (roof level)	10/19/08	1	3.060	Asbestos	PCME	EMSL	10/20/08	< 0.00081	No	No	
ASBESTOS-ST13-10/19/08	030837169-0008	Marriott Hotel, 38th Floor (roof level)	10/19/08	1	3.000	Asbestos	PCME	EMSL	10/20/08	< 0.00082	No	No	
ASBESTOS-ST14-10/19/08	030837169-0009	West Face - South end at corner (scaffolding level)	10/19/08	1	3.190	Asbestos	PCME	EMSL	10/20/08	< 0.00077	No	No	
ASBESTOS-ST15-10/19/08	030837169-0010	South Face - East end at corner (scaffolding level)	10/19/08	1	3.250	Asbestos	PCME	EMSL	10/20/08	< 0.00076	No	No	
ASBESTOS-ST16-10/19/08	030837169-0011	East Face - North end at corner (scaffolding level)	10/19/08	1	3.230	Asbestos	PCME	EMSL	10/20/08	< 0.00076	No	No	
ASBESTOS-ST17-10/19/08	030837169-0012	North Face - West end at corner (scaffolding level)	10/19/08	1	3.180	Asbestos	PCME	EMSL	10/20/08	< 0.00078	No	No	
ASBESTOS-ST1-10/20/08	030837331-0001	Southwest Area (sidewalk bridge level)	10/20/08	1	3.070	Asbestos	PCME	EMSL	10/21/08	< 0.00080	No	No	
ASBESTOS-ST2-10/20/08	030837331-0002	Southeast Area (sidewalk bridge level)	10/20/08	1	3.050	Asbestos	PCME	EMSL	10/21/08	< 0.00081	No	No	
ASBESTOS-ST4-10/20/08	030837331-0003	Northwest Area (street-level)	10/20/08	1	3.050	Asbestos	PCME	EMSL	10/21/08	< 0.00081	No	No	
ASBESTOS-ST5-10/20/08	030837331-0004	Firehouse #10 (roof level)	10/20/08	1	3.070	Asbestos	PCME	EMSL	10/21/08	< 0.00080	No	No	
ASBESTOS-ST10-10/20/08	030837331-0005	North Side Sidewalk Bridge	10/20/08	1	3.000	Asbestos	PCME	EMSL	10/21/08	< 0.00082	No	No	
ASBESTOS-ST11-10/20/08	030837331-0006	90 Trinity Place (roof level)	10/20/08	1	3.070	Asbestos	PCME	EMSL	10/21/08	< 0.00080	No	No	
ASBESTOS-ST12-10/20/08	030837331-0007	110 Greenwich Street (roof level)	10/20/08	1	3.090	Asbestos	PCME	EMSL	10/21/08	< 0.00080	No	No	
ASBESTOS-ST13-10/20/08	030837331-0008	Marriott Hotel, 38th Floor (roof level)	10/20/08	1	3.140	Asbestos	PCME	EMSL	10/21/08	< 0.00079	No	No	
ASBESTOS-ST14-10/20/08	030837331-0009	West Face - South end at corner (scaffolding level)	10/20/08	1	3.060	Asbestos	PCME	EMSL	10/21/08	< 0.00081	No	No	
ASBESTOS-ST15-10/20/08	030837331-0010	South Face - East end at corner (scaffolding level)	10/20/08	1	2.950	Asbestos	PCME	EMSL	10/21/08	< 0.00084	No	No	
ASBESTOS-ST16-10/20/08	030837331-0011	East Face - North end at corner (scaffolding level)	10/20/08	1	2.970	Asbestos	PCME	EMSL	10/21/08	< 0.00083	No	No	
ASBESTOS-ST17-10/20/08	030837331-0012	North Face - West end at corner (scaffolding level)	10/20/08	1	3.120	Asbestos	PCME	EMSL	10/21/08	< 0.00079	No	No	

Note:
1. Asbestos sample volume at Station 4 (Northwest Area (street-level)) on October 18, 2008 was reduced on account of temporary power failure; sample collection did not start until 1320 on October 18, 2008.