

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										<b>0.0009</b>	Air Quality Levels	Site Specific Trigger Levels	
										<b>NA</b>			
										<b>Target Air Quality Levels</b>			
										<b>EPA Site Specific Trigger Levels</b>			
ASBESTOS-ST1-10/20/06	030634664-0001	Southwest Area (sidewalk bridge level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST2-10/20/06	030634664-0002	Southeast Area (sidewalk bridge level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST4-10/20/06	030634664-0003	Northwest Area (street-level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST5-10/20/06	030634664-0004	Firehouse #10 (roof level)	10/20/06	1	2.770	Asbestos	PCME	EMSL	10/23/06	< 0.00089	No	No	
ASBESTOS-ST10-10/20/06	030634664-0005	North Side Sidewalk Bridge	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST11-10/20/06	030634664-0006	90 Trinity Place (roof level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST12-10/20/06	030634664-0007	110 Greenwich Street (roof level)	10/20/06	1	2.960	Asbestos	PCME	EMSL	10/23/06	< 0.00083	No	No	
ASBESTOS-ST13-10/20/06	030634664-0008	Marriott Hotel, 38th Floor (roof level)	10/20/06	1	2.960	Asbestos	PCME	EMSL	10/23/06	< 0.00083	No	No	
ASBESTOS-ST14-10/20/06	030634664-0009	West Face - South end at corner (scaffolding level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST15-10/20/06	030634664-0010	South Face - East end at corner (scaffolding level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST16-10/20/06	030634664-0011	East Face - North end at corner (scaffolding level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST17-10/20/06	030634664-0012	North Face - West end at corner (scaffolding level)	10/20/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST1-10/21/06	030634666-0001	Southwest Area (sidewalk bridge level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST2-10/21/06	030634666-0002	Southeast Area (sidewalk bridge level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST4-10/21/06	030634666-0003	Northwest Area (street-level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST5-10/21/06	030634666-0004	Firehouse #10 (roof level)	10/21/06	1	3.010	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST10-10/21/06	030634666-0005	North Side Sidewalk Bridge	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST11-10/21/06	030634666-0006	90 Trinity Place (roof level)	10/21/06	1	3.070	Asbestos	PCME	EMSL	10/23/06	< 0.00080	No	No	
ASBESTOS-ST12-10/21/06	030634666-0007	110 Greenwich Street (roof level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST13-10/21/06	030634666-0008	Marriott Hotel, 38th Floor (roof level)	10/21/06	1	3.040	Asbestos	PCME	EMSL	10/23/06	< 0.00081	No	No	
ASBESTOS-ST14-10/21/06	030634666-0009	West Face - South end at corner (scaffolding level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST15-10/21/06	030634666-0010	South Face - East end at corner (scaffolding level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST16-10/21/06	030634666-0011	East Face - North end at corner (scaffolding level)	10/21/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST17-10/21/06	030634666-0012	North Face - West end at corner (scaffolding level)	10/21/06	1	3.010	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST1-10/22/06	030634667-0001	Southwest Area (sidewalk bridge level)	10/22/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST2-10/22/06	030634667-0002	Southeast Area (sidewalk bridge level)	10/22/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST4-10/22/06	030634667-0003	Northwest Area (street-level)	10/22/06	1	3.090	Asbestos	PCME	EMSL	10/23/06	< 0.00080	No	No	
ASBESTOS-ST5-10/22/06	030634667-0004	Firehouse #10 (roof level)	10/22/06	1	3.040	Asbestos	PCME	EMSL	10/23/06	< 0.00081	No	No	
ASBESTOS-ST10-10/22/06	030634667-0005	North Side Sidewalk Bridge	10/22/06	1	2.900	Asbestos	PCME	EMSL	10/23/06	< 0.00085	No	No	
ASBESTOS-ST11-10/22/06	030634667-0006	90 Trinity Place (roof level)	10/22/06	1	3.040	Asbestos	PCME	EMSL	10/23/06	< 0.00081	No	No	
ASBESTOS-ST12-10/22/06	030634667-0007	110 Greenwich Street (roof level)	10/22/06	1	3.060	Asbestos	PCME	EMSL	10/23/06	< 0.00081	No	No	
ASBESTOS-ST13-10/22/06	030634667-0008	Marriott Hotel, 38th Floor (roof level)	10/22/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST14-10/22/06	030634667-0009	West Face - South end at corner (scaffolding level)	10/22/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST15-10/22/06	030634667-0010	South Face - East end at corner (scaffolding level)	10/22/06	1	3.040	Asbestos	PCME	EMSL	10/23/06	< 0.00081	No	No	
ASBESTOS-ST16-10/22/06	030634667-0011	East Face - North end at corner (scaffolding level)	10/22/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	
ASBESTOS-ST17-10/22/06	030634667-0012	North Face - West end at corner (scaffolding level)	10/22/06	1	3.020	Asbestos	PCME	EMSL	10/23/06	< 0.00082	No	No	