

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-10/24/07	030734814-0001	Southwest Area (sidewalk bridge level)	10/24/07	1	3.010	Asbestos	PCME	EMSL	10/25/07	< 0.00089	No	No	
ASBESTOS-ST2-10/24/07	030734814-0002	Southeast Area (sidewalk bridge level)	10/24/07	1	3.010	Asbestos	PCME	EMSL	10/25/07	< 0.00089	No	No	
ASBESTOS-ST4-10/24/07	030734814-0003	Northwest Area (street-level)	10/24/07	1	2.960	Asbestos	PCME	EMSL	10/25/07	< 0.00083	No	No	
ASBESTOS-ST5-10/24/07	030734814-0004	Firehouse #10 (roof level)	10/24/07	1	3.010	Asbestos	PCME	EMSL	10/25/07	< 0.00089	No	No	
ASBESTOS-ST10-10/24/07	030734814-0005	North Side Sidewalk Bridge	10/24/07	1	2.990	Asbestos	PCME	EMSL	10/25/07	< 0.00083	No	No	
ASBESTOS-ST11-10/24/07	030734814-0006	90 Trinity Place (roof level)	10/24/07	1	3.060	Asbestos	PCME	EMSL	10/25/07	< 0.00088	No	No	
ASBESTOS-ST12-10/24/07	030734814-0007	110 Greenwich Street (roof level)	10/24/07	1	3.040	Asbestos	PCME	EMSL	10/25/07	< 0.00081	No	No	
ASBESTOS-ST13-10/24/07	030734814-0008	Marriott Hotel, 38th Floor (roof level)	10/24/07	1	3.000	Asbestos	PCME	EMSL	10/25/07	< 0.00082	No	No	
ASBESTOS-ST14-10/24/07	030734814-0009	West Face - South end at corner (scaffolding level)	10/24/07	1	2.990	Asbestos	PCME	EMSL	10/25/07	< 0.00083	No	No	
ASBESTOS-ST15-10/24/07	030734814-0010	South Face - East end at corner (scaffolding level)	10/24/07	1	2.950	Asbestos	PCME	EMSL	10/25/07	< 0.00084	No	No	
ASBESTOS-ST16-10/24/07	030734814-0011	East Face - North end at corner (scaffolding level)	10/24/07	1	3.040	Asbestos	PCME	EMSL	10/25/07	< 0.00081	No	No	
ASBESTOS-ST17-10/24/07	030734814-0012	North Face - West end at corner (scaffolding level)	10/24/07	1	2.840	Asbestos	PCME	EMSL	10/25/07	< 0.00087	No	No	
ASBESTOS-ST1-10/25/07	030734915-0001	Southwest Area (sidewalk bridge level)	10/25/07	1	2.930	Asbestos	PCME	EMSL	10/26/07	< 0.00084	No	No	
ASBESTOS-ST2-10/25/07	030734915-0002	Southeast Area (sidewalk bridge level)	10/25/07	1	3.090	Asbestos	PCME	EMSL	10/26/07	< 0.00080	No	No	
ASBESTOS-ST4-10/25/07	030734915-0003	Northwest Area (street-level)	10/25/07	1	2.990	Asbestos	PCME	EMSL	10/26/07	< 0.00083	No	No	
ASBESTOS-ST5-10/25/07	030734915-0004	Firehouse #10 (roof level)	10/25/07	1	3.000	Asbestos	PCME	EMSL	10/26/07	< 0.00082	No	No	
ASBESTOS-ST10-10/25/07	030734915-0005	North Side Sidewalk Bridge	10/25/07	1	3.040	Asbestos	PCME	EMSL	10/26/07	< 0.00081	No	No	
ASBESTOS-ST100-10/25/07	030734915-0013	Station 10 Field Duplicate	10/25/07	1	3.030	Asbestos	PCME	EMSL	10/26/07	< 0.00081	No	No	
ASBESTOS-ST11-10/25/07	030734915-0006	90 Trinity Place (roof level)	10/25/07	1	3.000	Asbestos	PCME	EMSL	10/26/07	< 0.00082	No	No	
ASBESTOS-ST12-10/25/07	030734915-0007	110 Greenwich Street (roof level)	10/25/07	1	3.040	Asbestos	PCME	EMSL	10/26/07	< 0.00081	No	No	
ASBESTOS-ST13-10/25/07	030734915-0008	Marriott Hotel, 38th Floor (roof level)	10/25/07	1	3.120	Asbestos	PCME	EMSL	10/26/07	< 0.00079	No	No	
ASBESTOS-ST14-10/25/07	030734915-0009	West Face - South end at corner (scaffolding level)	10/25/07	1	3.020	Asbestos	PCME	EMSL	10/26/07	< 0.00082	No	No	
ASBESTOS-ST15-10/25/07	030734915-0010	South Face - East end at corner (scaffolding level)	10/25/07	1	3.060	Asbestos	PCME	EMSL	10/26/07	< 0.00081	No	No	
ASBESTOS-ST16-10/25/07	030734915-0011	East Face - North end at corner (scaffolding level)	10/25/07	1	3.010	Asbestos	PCME	EMSL	10/26/07	< 0.00082	No	No	
ASBESTOS-ST17-10/25/07	030734915-0012	North Face - West end at corner (scaffolding level)	10/25/07	1	2.990	Asbestos	PCME	EMSL	10/26/07	< 0.00083	No	No	
ASBESTOS-ST1-10/26/07	030734987-0001	Southwest Area (sidewalk bridge level)	10/26/07	1	3.020	Asbestos	PCME	EMSL	10/27/07	< 0.00082	No	No	
ASBESTOS-ST2-10/26/07	030734987-0002	Southeast Area (sidewalk bridge level)	10/26/07	1	3.010	Asbestos	PCME	EMSL	10/27/07	< 0.00082	No	No	
ASBESTOS-ST4-10/26/07	030734987-0003	Northwest Area (street-level)	10/26/07	1	3.060	Asbestos	PCME	EMSL	10/27/07	< 0.00081	No	No	
ASBESTOS-ST5-10/26/07	030734987-0004	Firehouse #10 (roof level)	10/26/07	1	3.150	Asbestos	PCME	EMSL	10/27/07	< 0.00078	No	No	
ASBESTOS-ST10-10/26/07	030734987-0005	North Side Sidewalk Bridge	10/26/07	1	3.030	Asbestos	PCME	EMSL	10/27/07	< 0.00081	No	No	
ASBESTOS-ST11-10/26/07	030734987-0006	90 Trinity Place (roof level)	10/26/07	1	2.960	Asbestos	PCME	EMSL	10/27/07	< 0.00083	No	No	
ASBESTOS-ST12-10/26/07	030734987-0007	110 Greenwich Street (roof level)	10/26/07	1	2.960	Asbestos	PCME	EMSL	10/27/07	< 0.00083	No	No	
ASBESTOS-ST13-10/26/07	030734987-0008	Marriott Hotel, 38th Floor (roof level)	10/26/07	1	3.090	Asbestos	PCME	EMSL	10/27/07	< 0.00080	No	No	
ASBESTOS-ST14-10/26/07	030734987-0009	West Face - South end at corner (scaffolding level)	10/26/07	1	2.990	Asbestos	PCME	EMSL	10/27/07	< 0.00083	No	No	
ASBESTOS-ST15-10/26/07	030734987-0010	South Face - East end at corner (scaffolding level)	10/26/07	1	3.110	Asbestos	PCME	EMSL	10/27/07	< 0.00079	No	No	
ASBESTOS-ST16-10/26/07	030734987-0011	East Face - North end at corner (scaffolding level)	10/26/07	1	3.090	Asbestos	PCME	EMSL	10/27/07	< 0.00080	No	No	
ASBESTOS-ST17-10/26/07	030734987-0012	North Face - West end at corner (scaffolding level)	10/26/07	1	3.040	Asbestos	PCME	EMSL	10/27/07	< 0.00081	No	No	