

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										<b>0.0009</b>	Air Quality Levels	Site Specific Trigger Levels	
										<b>NA</b>			
ASBESTOS-ST1-10/29/07	030735202-0001	Southwest Area (sidewalk bridge level)	10/29/07	1	3.21	Asbestos	PCME	EMSL	10/30/07	< 0.00084	No	No	
ASBESTOS-ST2-10/29/07	030735202-0002	Southeast Area (sidewalk bridge level)	10/29/07	1	2.99	Asbestos	PCME	EMSL	10/30/07	< 0.00083	No	No	
ASBESTOS-ST4-10/29/07	030735202-0003	Northwest Area (street-level)	10/29/07	1	3.06	Asbestos	PCME	EMSL	10/30/07	< 0.00088	No	No	
ASBESTOS-ST5-10/29/07	030735202-0004	Firehouse #10 (roof level)	10/29/07	1	3.12	Asbestos	PCME	EMSL	10/30/07	< 0.00079	No	No	
ASBESTOS-ST10-10/29/07	030735202-0005	North Side Sidewalk Bridge	10/29/07	1	3.00	Asbestos	PCME	EMSL	10/30/07	< 0.00082	No	No	
ASBESTOS-ST11-10/29/07	030735202-0006	90 Trinity Place (roof level)	10/29/07	1	3.00	Asbestos	PCME	EMSL	10/30/07	< 0.00082	No	No	
ASBESTOS-ST12-10/29/07	030735202-0007	110 Greenwich Street (roof level)	10/29/07	1	3.04	Asbestos	PCME	EMSL	10/30/07	< 0.00081	No	No	
ASBESTOS-ST13-10/29/07	030735202-0008	Marriott Hotel, 38th Floor (roof level)	10/29/07	1	3.00	Asbestos	PCME	EMSL	10/30/07	< 0.00082	No	No	
ASBESTOS-ST14-10/29/07	030735202-0009	West Face - South end at corner (scaffolding level)	10/29/07	1	3.15	Asbestos	PCME	EMSL	10/30/07	< 0.00078	No	No	
ASBESTOS-ST15-10/29/07	030735202-0010	South Face - East end at corner (scaffolding level)	10/29/07	1	3.00	Asbestos	PCME	EMSL	10/30/07	< 0.00082	No	No	
ASBESTOS-ST16-10/29/07	030735202-0011	East Face - North end at corner (scaffolding level)	10/29/07	1	3.02	Asbestos	PCME	EMSL	10/30/07	< 0.00082	No	No	
ASBESTOS-ST17-10/29/07	030735202-0012	North Face - West end at corner (scaffolding level)	10/29/07	1	2.97	Asbestos	PCME	EMSL	10/30/07	< 0.00083	No	No	
ASBESTOS-ST1-10/30/07	030735310-0001	Southwest Area (sidewalk bridge level)	10/30/07	1	2.95	Asbestos	PCME	EMSL	10/31/07	< 0.00084	No	No	
ASBESTOS-ST2-10/30/07	030735310-0002	Southeast Area (sidewalk bridge level)	10/30/07	1	3.02	Asbestos	PCME	EMSL	10/31/07	< 0.00082	No	No	
ASBESTOS-ST4-10/30/07	030735310-0003	Northwest Area (street-level)	10/30/07	1	3.02	Asbestos	PCME	EMSL	10/31/07	< 0.00082	No	No	
ASBESTOS-ST5-10/30/07	030735310-0004	Firehouse #10 (roof level)	10/30/07	1	3.00	Asbestos	PCME	EMSL	10/31/07	< 0.00082	No	No	
ASBESTOS-ST10-10/30/07	030735310-0005	North Side Sidewalk Bridge	10/30/07	1	3.02	Asbestos	PCME	EMSL	10/31/07	< 0.00082	No	No	
ASBESTOS-ST11-10/30/07	030735310-0006	90 Trinity Place (roof level)	10/30/07	1	3.02	Asbestos	PCME	EMSL	10/31/07	< 0.00082	No	No	
ASBESTOS-ST12-10/30/07	030735310-0007	110 Greenwich Street (roof level)	10/30/07	1	3.08	Asbestos	PCME	EMSL	10/31/07	< 0.00080	No	No	
ASBESTOS-ST13-10/30/07	030735310-0008	Marriott Hotel, 38th Floor (roof level)	10/30/07	1	3.15	Asbestos	PCME	EMSL	10/31/07	< 0.00085	No	No	
ASBESTOS-ST14-10/30/07	030735310-0009	West Face - South end at corner (scaffolding level)	10/30/07	1	3.06	Asbestos	PCME	EMSL	10/31/07	< 0.00081	No	No	
ASBESTOS-ST15-10/30/07	030735310-0010	South Face - East end at corner (scaffolding level)	10/30/07	1	2.99	Asbestos	PCME	EMSL	10/31/07	< 0.00083	No	No	
ASBESTOS-ST16-10/30/07	030735310-0011	East Face - North end at corner (scaffolding level)	10/30/07	1	3.04	Asbestos	PCME	EMSL	10/31/07	< 0.00081	No	No	
ASBESTOS-ST17-10/30/07	030735310-0012	North Face - West end at corner (scaffolding level)	10/30/07	1	3.09	Asbestos	PCME	EMSL	10/31/07	< 0.00080	No	No	