

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-10/29/08	030838634-0001	Southwest Area (sidewalk bridge level)	10/29/08	1	3.110	Asbestos	PCME	EMSL	10/30/08	< 0.00087	No	No	
ASBESTOS-ST2-10/29/08	030838634-0002	Southeast Area (sidewalk bridge level)	10/29/08	1	3.080	Asbestos	PCME	EMSL	10/30/08	< 0.00087	No	No	
ASBESTOS-ST4-10/29/08	030838634-0003	Northwest Area (street-level)	10/29/08	1	2.880	Asbestos	PCME	EMSL	10/30/08	< 0.00086	No	No	
ASBESTOS-ST5-10/29/08	030838634-0004	Firehouse #10 (roof level)	10/29/08	1	2.990	Asbestos	PCME	EMSL	10/30/08	< 0.00083	No	No	
ASBESTOS-ST10-10/29/08	030838634-0005	North Side Sidewalk Bridge	10/29/08	1	3.040	Asbestos	PCME	EMSL	10/30/08	< 0.00089	No	No	
ASBESTOS-ST11-10/29/08	030838634-0006	90 Trinity Place (roof level)	10/29/08	1	2.990	Asbestos	PCME	EMSL	10/30/08	< 0.00083	No	No	
ASBESTOS-ST12-10/29/08	030838634-0007	110 Greenwich Street (roof level)	10/29/08	1	3.050	Asbestos	PCME	EMSL	10/30/08	< 0.00081	No	No	
ASBESTOS-ST13-10/29/08	030838634-0008	Marriott Hotel, 38th Floor (roof level)	10/29/08	1	3.080	Asbestos	PCME	EMSL	10/30/08	< 0.00087	No	No	
ASBESTOS-ST14-10/29/08	030838634-0009	West Face - South end at corner (scaffolding level)	10/29/08	1	3.050	Asbestos	PCME	EMSL	10/30/08	< 0.00088	No	No	
ASBESTOS-ST15-10/29/08	030838634-0010	South Face - East end at corner (scaffolding level)	10/29/08	1	3.060	Asbestos	PCME	EMSL	10/30/08	< 0.00088	No	No	
ASBESTOS-ST16-10/29/08	030838634-0011	East Face - North end at corner (scaffolding level)	10/29/08	1	3.100	Asbestos	PCME	EMSL	10/30/08	< 0.00087	No	No	
ASBESTOS-ST17-10/29/08	030838634-0012	North Face - West end at corner (scaffolding level)	10/29/08	1	3.290	Asbestos	PCME	EMSL	10/30/08	< 0.00082	No	No	
ASBESTOS-ST1-10/30/08	030838781-0001	Southwest Area (sidewalk bridge level)	10/30/08	1	2.750	Asbestos	PCME	EMSL	10/31/08	< 0.00083	No	No	
ASBESTOS-ST2-10/30/08	030838781-0002	Southeast Area (sidewalk bridge level)	10/30/08	1	3.080	Asbestos	PCME	EMSL	10/31/08	< 0.00080	No	No	
ASBESTOS-ST4-10/30/08	030838781-0003	Northwest Area (street-level)	10/30/08	1	3.080	Asbestos	PCME	EMSL	10/31/08	< 0.00080	No	No	
ASBESTOS-ST5-10/30/08	030838781-0004	Firehouse #10 (roof level)	10/30/08	1	3.020	Asbestos	PCME	EMSL	10/31/08	< 0.00082	No	No	
ASBESTOS-ST10-10/30/08	030838781-0005	North Side Sidewalk Bridge	10/30/08	1	3.130	Asbestos	PCME	EMSL	10/31/08	< 0.00079	No	No	
ASBESTOS-ST11-10/30/08	030838781-0006	90 Trinity Place (roof level)	10/30/08	1	3.060	Asbestos	PCME	EMSL	10/31/08	< 0.00081	No	No	
ASBESTOS-ST12-10/30/08	030838781-0007	110 Greenwich Street (roof level)	10/30/08	1	3.060	Asbestos	PCME	EMSL	10/31/08	< 0.00081	No	No	
ASBESTOS-ST13-10/30/08	030838781-0008	Marriott Hotel, 38th Floor (roof level)	10/30/08	1	3.080	Asbestos	PCME	EMSL	10/31/08	< 0.00080	No	No	
ASBESTOS-ST14-10/30/08	030838781-0009	West Face - South end at corner (scaffolding level)	10/30/08	1	2.990	Asbestos	PCME	EMSL	10/31/08	< 0.00083	No	No	
ASBESTOS-ST15-10/30/08	030838781-0010	South Face - East end at corner (scaffolding level)	10/30/08	1	3.110	Asbestos	PCME	EMSL	10/31/08	< 0.00079	No	No	
ASBESTOS-ST16-10/30/08	030838781-0011	East Face - North end at corner (scaffolding level)	10/30/08	1	3.070	Asbestos	PCME	EMSL	10/31/08	< 0.00080	No	No	
ASBESTOS-ST17-10/30/08	030838781-0012	North Face - West end at corner (scaffolding level)	10/30/08	1	3.030	Asbestos	PCME	EMSL	10/31/08	< 0.00081	No	No	