

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-10/30/06	030635519-0001	Southwest Area (sidewalk bridge level)	10/30/06	1	3.020	Asbestos	PCME	EMSL	10/31/06	< 0.00082	No	No	
ASBESTOS-ST2-10/30/06	030635519-0002	Southeast Area (sidewalk bridge level)	10/30/06	1	3.020	Asbestos	PCME	EMSL	10/31/06	< 0.00082	No	No	
ASBESTOS-ST4-10/30/06	030635519-0003	Northwest Area (street-level)	10/30/06	1	3.040	Asbestos	PCME	EMSL	10/31/06	< 0.00081	No	No	
ASBESTOS-ST5-10/30/06	030635519-0004	Firehouse #10 (roof level)	10/30/06	1	3.020	Asbestos	PCME	EMSL	10/31/06	< 0.00082	No	No	
ASBESTOS-ST10-10/30/06	030635519-0005	North Side Sidewalk Bridge	10/30/06	1	3.020	Asbestos	PCME	EMSL	10/31/06	< 0.00082	No	No	
ASBESTOS-ST11-10/30/06	030635519-0006	90 Trinity Place (roof level)	10/30/06	1	3.020	Asbestos	PCME	EMSL	10/31/06	< 0.00082	No	No	
ASBESTOS-ST12-10/30/06	030635519-0007	110 Greenwich Street (roof level)	10/30/06	1	3.030	Asbestos	PCME	EMSL	10/31/06	< 0.00081	No	No	
ASBESTOS-ST13-10/30/06	030635519-0008	Marriott Hotel, 38th Floor (roof level)	10/30/06	1	3.020	Asbestos	PCME	EMSL	10/31/06	< 0.00082	No	No	
ASBESTOS-ST14-10/30/06	030635519-0009	West Face - South end at corner (scaffolding level)	10/30/06	1	3.060	Asbestos	PCME	EMSL	10/31/06	< 0.00081	No	No	
ASBESTOS-ST15-10/30/06	030635519-0010	South Face - East end at corner (scaffolding level)	10/30/06	1	2.840	Asbestos	PCME	EMSL	10/31/06	< 0.00087	No	No	
ASBESTOS-ST16-10/30/06	030635519-0011	East Face - North end at corner (scaffolding level)	10/30/06	1	2.960	Asbestos	PCME	EMSL	10/31/06	< 0.00083	No	No	
ASBESTOS-ST17-10/30/06	030635519-0012	North Face - West end at corner (scaffolding level)	10/30/06	1	3.040	Asbestos	PCME	EMSL	10/31/06	< 0.00081	No	No	
ASBESTOS-ST1-10/31/06	030635661-0001	Southwest Area (sidewalk bridge level)	10/31/06	1	2.900	Asbestos	PCME	EMSL	11/1/06	< 0.00079	No	No	
ASBESTOS-ST2-10/31/06	030635661-0002	Southeast Area (sidewalk bridge level)	10/31/06	1	2.960	Asbestos	PCME	EMSL	11/1/06	< 0.00083	No	No	
ASBESTOS-ST4-10/31/06	030635661-0003	Northwest Area (street-level)	10/31/06	1	3.090	Asbestos	PCME	EMSL	11/1/06	< 0.00080	No	No	
ASBESTOS-ST5-10/31/06	030635661-0004	Firehouse #10 (roof level)	10/31/06	1	3.050	Asbestos	PCME	EMSL	11/1/06	< 0.00081	No	No	
ASBESTOS-ST10-10/31/06	030635661-0005	North Side Sidewalk Bridge	10/31/06	1	3.060	Asbestos	PCME	EMSL	11/1/06	< 0.00081	No	No	
ASBESTOS-ST100-10/31/06	030635661-0013	Station 10 Field Duplicate	10/31/06	1	3.010	Asbestos	PCME	EMSL	11/1/06	< 0.00082	No	No	
ASBESTOS-ST11-10/31/06	030635661-0006	90 Trinity Place (roof level)	10/31/06	1	3.020	Asbestos	PCME	EMSL	11/1/06	< 0.00082	No	No	
ASBESTOS-ST12-10/31/06	030635661-0007	110 Greenwich Street (roof level)	10/31/06	1	3.040	Asbestos	PCME	EMSL	11/1/06	< 0.00081	No	No	
ASBESTOS-ST13-10/31/06	030635661-0008	Marriott Hotel, 38th Floor (roof level)	10/31/06	1	2.840	Asbestos	PCME	EMSL	11/1/06	< 0.00087	No	No	
ASBESTOS-ST14-10/31/06	030635661-0009	West Face - South end at corner (scaffolding level)	10/31/06	1	3.040	Asbestos	PCME	EMSL	11/1/06	< 0.00081	No	No	
ASBESTOS-ST15-10/31/06	030635661-0010	South Face - East end at corner (scaffolding level)	10/31/06	1	2.960	Asbestos	PCME	EMSL	11/1/06	< 0.00083	No	No	
ASBESTOS-ST16-10/31/06	030635661-0011	East Face - North end at corner (scaffolding level)	10/31/06	1	2.960	Asbestos	PCME	EMSL	11/1/06	< 0.00083	No	No	
ASBESTOS-ST17-10/31/06	030635661-0012	North Face - West end at corner (scaffolding level)	10/31/06	1	3.040	Asbestos	PCME	EMSL	11/1/06	< 0.00081	No	No	