

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-11/1/07	030735547-0001	Southwest Area (sidewalk bridge level)	11/1/07	1	3.020	Asbestos	PCME	EMSL	11/2/07	< 0.00082	No	No	
ASBESTOS-ST2-11/1/07	030735547-0002	Southeast Area (sidewalk bridge level)	11/1/07	1	3.010	Asbestos	PCME	EMSL	11/2/07	< 0.00082	No	No	
ASBESTOS-ST4-11/1/07	030735547-0003	Northwest Area (street-level)	11/1/07	1	3.000	Asbestos	PCME	EMSL	11/2/07	< 0.00082	No	No	
ASBESTOS-ST5-11/1/07	030735547-0004	Firehouse #10 (roof level)	11/1/07	1	3.010	Asbestos	PCME	EMSL	11/2/07	< 0.00082	No	No	
ASBESTOS-ST10-11/1/07	030735547-0005	North Side Sidewalk Bridge	11/1/07	1	3.030	Asbestos	PCME	EMSL	11/2/07	< 0.00081	No	No	
ASBESTOS-ST11-11/1/07	030735547-0006	90 Trinity Place (roof level)	11/1/07	1	3.010	Asbestos	PCME	EMSL	11/2/07	< 0.00082	No	No	
ASBESTOS-ST12-11/1/07	030735547-0007	110 Greenwich Street (roof level)	11/1/07	1	3.060	Asbestos	PCME	EMSL	11/2/07	< 0.00081	No	No	
ASBESTOS-ST13-11/1/07	030735547-0008	Marriott Hotel, 38th Floor (roof level)	11/1/07	1	3.100	Asbestos	PCME	EMSL	11/2/07	< 0.00080	No	No	
ASBESTOS-ST14-11/1/07	030735547-0009	West Face - South end at corner (scaffolding level)	11/1/07	1	3.010	Asbestos	PCME	EMSL	11/2/07	< 0.00082	No	No	
ASBESTOS-ST15-11/1/07	030735547-0010	South Face - East end at corner (scaffolding level)	11/1/07	1	2.960	Asbestos	PCME	EMSL	11/2/07	< 0.00083	No	No	
ASBESTOS-ST16-11/1/07	030735547-0011	East Face - North end at corner (scaffolding level)	11/1/07	1	3.040	Asbestos	PCME	EMSL	11/2/07	< 0.00081	No	No	
ASBESTOS-ST17-11/1/07	030735547-0012	North Face - West end at corner (scaffolding level)	11/1/07	1	2.990	Asbestos	PCME	EMSL	11/2/07	< 0.00083	No	No	
ASBESTOS-ST1-11/2/07	030735649-0001	Southwest Area (sidewalk bridge level)	11/2/07	1	2.980	Asbestos	PCME	EMSL	11/3/07	< 0.00083	No	No	
ASBESTOS-ST2-11/2/07	030735649-0002	Southeast Area (sidewalk bridge level)	11/2/07	1	3.000	Asbestos	PCME	EMSL	11/3/07	< 0.00082	No	No	
ASBESTOS-ST5-11/2/07	030735649-0003	Firehouse #10 (roof level)	11/2/07	1	3.010	Asbestos	PCME	EMSL	11/3/07	< 0.00082	No	No	
ASBESTOS-ST10-11/2/07	030735649-0004	North Side Sidewalk Bridge	11/2/07	1	3.030	Asbestos	PCME	EMSL	11/3/07	< 0.00081	No	No	
ASBESTOS-ST100-11/2/07	030735649-0012	Station 10 Field Duplicate	11/2/07	1	3.020	Asbestos	PCME	EMSL	11/3/07	< 0.00082	No	No	
ASBESTOS-ST11-11/2/07	030735649-0005	90 Trinity Place (roof level)	11/2/07	1	3.000	Asbestos	PCME	EMSL	11/3/07	< 0.00082	No	No	
ASBESTOS-ST12-11/2/07	030735649-0006	110 Greenwich Street (roof level)	11/2/07	1	3.030	Asbestos	PCME	EMSL	11/3/07	< 0.00081	No	No	
ASBESTOS-ST13-11/2/07	030735649-0007	Marriott Hotel, 38th Floor (roof level)	11/2/07	1	3.010	Asbestos	PCME	EMSL	11/3/07	< 0.00082	No	No	
ASBESTOS-ST14-11/2/07	030735649-0008	West Face - South end at corner (scaffolding level)	11/2/07	1	3.000	Asbestos	PCME	EMSL	11/3/07	< 0.00082	No	No	
ASBESTOS-ST15-11/2/07	030735649-0009	South Face - East end at corner (scaffolding level)	11/2/07	1	3.030	Asbestos	PCME	EMSL	11/3/07	< 0.00081	No	No	
ASBESTOS-ST16-11/2/07	030735649-0010	East Face - North end at corner (scaffolding level)	11/2/07	1	3.060	Asbestos	PCME	EMSL	11/3/07	< 0.00081	No	No	
ASBESTOS-ST17-11/2/07	030735649-0011	North Face - West end at corner (scaffolding level)	11/2/07	1	3.060	Asbestos	PCME	EMSL	11/3/07	< 0.00081	No	No	
ASBESTOS-ST1-11/3/07	030735742-0001	Southwest Area (sidewalk bridge level)	11/3/07	1	3.330	Asbestos	PCME	EMSL	11/5/07	< 0.00081	No	No	
ASBESTOS-ST2-11/3/07	030735742-0002	Southeast Area (sidewalk bridge level)	11/3/07	1	3.290	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST4-11/3/07	030735742-0003	Northwest Area (street-level)	11/3/07	1	3.100	Asbestos	PCME	EMSL	11/5/07	< 0.00087	No	No	
ASBESTOS-ST5-11/3/07	030735742-0004	Firehouse #10 (roof level)	11/3/07	1	3.300	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST10-11/3/07	030735742-0005	North Side Sidewalk Bridge	11/3/07	1	3.200	Asbestos	PCME	EMSL	11/5/07	< 0.00084	No	No	
ASBESTOS-ST11-11/3/07	030735742-0006	90 Trinity Place (roof level)	11/3/07	1	3.180	Asbestos	PCME	EMSL	11/5/07	< 0.00085	No	No	
ASBESTOS-ST12-11/3/07	030735742-0007	110 Greenwich Street (roof level)	11/3/07	1	3.170	Asbestos	PCME	EMSL	11/5/07	< 0.00085	No	No	
ASBESTOS-ST13-11/3/07	030735742-0008	Marriott Hotel, 38th Floor (roof level)	11/3/07	1	3.190	Asbestos	PCME	EMSL	11/5/07	< 0.00084	No	No	
ASBESTOS-ST14-11/3/07	030735742-0009	West Face - South end at corner (scaffolding level)	11/3/07	1	3.230	Asbestos	PCME	EMSL	11/5/07	< 0.00083	No	No	
ASBESTOS-ST15-11/3/07	030735742-0010	South Face - East end at corner (scaffolding level)	11/3/07	1	3.150	Asbestos	PCME	EMSL	11/5/07	< 0.00085	No	No	
ASBESTOS-ST16-11/3/07	030735742-0011	East Face - North end at corner (scaffolding level)	11/3/07	1	3.160	Asbestos	PCME	EMSL	11/5/07	< 0.00085	No	No	
ASBESTOS-ST17-11/3/07	030735742-0012	North Face - West end at corner (scaffolding level)	11/3/07	1	3.150	Asbestos	PCME	EMSL	11/5/07	< 0.00085	No	No	
ASBESTOS-ST1-11/4/07	030735744-0001	Southwest Area (sidewalk bridge level)	11/4/07	1	3.000	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST2-11/4/07	030735744-0002	Southeast Area (sidewalk bridge level)	11/4/07	1	3.010	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST4-11/4/07	030735744-0003	Northwest Area (street-level)	11/4/07	1	3.020	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST5-11/4/07	030735744-0004	Firehouse #10 (roof level)	11/4/07	1	3.150	Asbestos	PCME	EMSL	11/5/07	< 0.00078	No	No	
ASBESTOS-ST10-11/4/07	030735744-0005	North Side Sidewalk Bridge	11/4/07	1	2.960	Asbestos	PCME	EMSL	11/5/07	< 0.00083	No	No	
ASBESTOS-ST11-11/4/07	030735744-0006	90 Trinity Place (roof level)	11/4/07	1	3.010	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST12-11/4/07	030735744-0007	110 Greenwich Street (roof level)	11/4/07	1	3.010	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST13-11/4/07	030735744-0008	Marriott Hotel, 38th Floor (roof level)	11/4/07	1	3.110	Asbestos	PCME	EMSL	11/5/07	< 0.00079	No	No	
ASBESTOS-ST14-11/4/07	030735744-0009	West Face - South end at corner (scaffolding level)	11/4/07	1	3.090	Asbestos	PCME	EMSL	11/5/07	< 0.00080	No	No	
ASBESTOS-ST15-11/4/07	030735744-0010	South Face - East end at corner (scaffolding level)	11/4/07	1	3.010	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST16-11/4/07	030735744-0011	East Face - North end at corner (scaffolding level)	11/4/07	1	3.020	Asbestos	PCME	EMSL	11/5/07	< 0.00082	No	No	
ASBESTOS-ST17-11/4/07	030735744-0012	North Face - West end at corner (scaffolding level)	11/4/07	1	3.150	Asbestos	PCME	EMSL	11/5/07	< 0.00085	No	No	

Note:

1. Asbestos sample at Station 4 (Northwest Area [street-level]) on November 2, 2007 was not available for analysis on account of power failure.