

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-11/5/08	030839537-0001	Southwest Area (sidewalk bridge level)	11/5/08	1	3.070	Asbestos	PCME	EMSL	11/6/08	< 0.00080	No	No	
ASBESTOS-ST2-11/5/08	030839537-0002	Southeast Area (sidewalk bridge level)	11/5/08	1	3.010	Asbestos	PCME	EMSL	11/6/08	< 0.00082	No	No	
ASBESTOS-ST4-11/5/08	030839537-0003	Northwest Area (street-level)	11/5/08	1	3.040	Asbestos	PCME	EMSL	11/6/08	< 0.00081	No	No	
ASBESTOS-ST5-11/5/08	030839537-0004	Firehouse #10 (roof level)	11/5/08	1	3.040	Asbestos	PCME	EMSL	11/6/08	< 0.00081	No	No	
ASBESTOS-ST10-11/5/08	030839537-0005	North Side Sidewalk Bridge	11/5/08	1	3.090	Asbestos	PCME	EMSL	11/6/08	< 0.00080	No	No	
ASBESTOS-ST11-11/5/08	030839537-0006	90 Trinity Place (roof level)	11/5/08	1	2.990	Asbestos	PCME	EMSL	11/6/08	< 0.00083	No	No	
ASBESTOS-ST12-11/5/08	030839537-0007	110 Greenwich Street (roof level)	11/5/08	1	3.040	Asbestos	PCME	EMSL	11/6/08	< 0.00081	No	No	
ASBESTOS-ST13-11/5/08	030839537-0008	Marriott Hotel, 38th Floor (roof level)	11/5/08	1	3.080	Asbestos	PCME	EMSL	11/6/08	< 0.00080	No	No	
ASBESTOS-ST14-11/5/08	030839537-0009	West Face - South end at corner (scaffolding level)	11/5/08	1	3.070	Asbestos	PCME	EMSL	11/6/08	< 0.00080	No	No	
ASBESTOS-ST15-11/5/08	030839537-0010	South Face - East end at corner (scaffolding level)	11/5/08	1	3.090	Asbestos	PCME	EMSL	11/6/08	< 0.00080	No	No	
ASBESTOS-ST16-11/5/08	030839537-0011	East Face - North end at corner (scaffolding level)	11/5/08	1	3.140	Asbestos	PCME	EMSL	11/6/08	< 0.00079	No	No	
ASBESTOS-ST17-11/5/08	030839537-0012	North Face - West end at corner (scaffolding level)	11/5/08	1	3.020	Asbestos	PCME	EMSL	11/6/08	< 0.00082	No	No	
ASBESTOS-ST1-11/06/08	030839671-0001	Southwest Area (sidewalk bridge level)	11/6/08	1	2.990	Asbestos	PCME	EMSL	11/7/08	< 0.00083	No	No	
ASBESTOS-ST2-11/06/08	030839671-0002	Southeast Area (sidewalk bridge level)	11/6/08	1	3.040	Asbestos	PCME	EMSL	11/7/08	< 0.00081	No	No	
ASBESTOS-ST4-11/06/08	030839671-0003	Northwest Area (street-level)	11/6/08	1	3.040	Asbestos	PCME	EMSL	11/7/08	< 0.00081	No	No	
ASBESTOS-ST5-11/06/08	030839671-0004	Firehouse #10 (roof level)	11/6/08	1	3.040	Asbestos	PCME	EMSL	11/7/08	< 0.00081	No	No	
ASBESTOS-ST10-11/06/08	030839671-0005	North Side Sidewalk Bridge	11/6/08	1	3.020	Asbestos	PCME	EMSL	11/7/08	< 0.00082	No	No	
ASBESTOS-ST11-11/06/08	030839671-0006	90 Trinity Place (roof level)	11/6/08	1	3.050	Asbestos	PCME	EMSL	11/7/08	< 0.00081	No	No	
ASBESTOS-ST12-11/06/08	030839671-0007	110 Greenwich Street (roof level)	11/6/08	1	2.970	Asbestos	PCME	EMSL	11/7/08	< 0.00083	No	No	
ASBESTOS-ST13-11/06/08	030839671-0008	Marriott Hotel, 38th Floor (roof level)	11/6/08	1	3.080	Asbestos	PCME	EMSL	11/7/08	< 0.00080	No	No	
ASBESTOS-ST14-11/06/08	030839671-0009	West Face - South end at corner (scaffolding level)	11/6/08	1	2.970	Asbestos	PCME	EMSL	11/7/08	< 0.00083	No	No	
ASBESTOS-ST15-11/06/08	030839671-0010	South Face - East end at corner (scaffolding level)	11/6/08	1	3.050	Asbestos	PCME	EMSL	11/7/08	< 0.00081	No	No	
ASBESTOS-ST16-11/06/08	030839671-0011	East Face - North end at corner (scaffolding level)	11/6/08	1	3.100	Asbestos	PCME	EMSL	11/7/08	< 0.00087	No	No	
ASBESTOS-ST17-11/06/08	030839671-0012	North Face - West end at corner (scaffolding level)	11/6/08	1	3.060	Asbestos	PCME	EMSL	11/7/08	< 0.00081	No	No	