

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	EPA Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-11/8/05	030533573-0001	Southwest Area (street-level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	Station 4 result obtained from SEM analysis due to overloading of filter.
ASBESTOS-ST2-11/8/05	030533573-0002	Southeast Area (sidewalk bridge level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	
ASBESTOS-ST4-11/8/05	030533573-0003	Northwest Area (street-level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	0.00080	No	No	
ASBESTOS-ST5-11/8/05	030533573-0004	Firehouse #10 (roof level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	
ASBESTOS-ST10-11/8/05	030533573-0005	North Side Sidewalk Bridge	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	
ASBESTOS-ST11-11/8/05	030533573-0006	90 Trinity Place (roof level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	
ASBESTOS-ST12-11/8/05	030533573-0007	110 Greenwich Street (roof level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	
ASBESTOS-ST13-11/8/05	030533573-0008	Marriott Hotel, 38th Floor (roof level)	11/8/05	1	2.970	Asbestos	PCME	EMSL	11/9/05	< 0.00083	No	No	
ASBESTOS-ST1-11/10/05	030533844-0001	Southwest Area (street-level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST2-11/10/05	030533844-0002	Southeast Area (sidewalk bridge level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST4-11/10/05	030533844-0003	Northwest Area (street-level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST5-11/10/05	030533844-0004	Firehouse #10 (roof level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST10-11/10/05	030533844-0005	North Side Sidewalk Bridge	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST11-11/10/05	030533844-0006	90 Trinity Place (roof level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST12-11/10/05	030533844-0007	110 Greenwich Street (roof level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST13-11/10/05	030533844-0008	Marriott Hotel, 38th Floor (roof level)	11/10/05	1	2.970	Asbestos	PCME	EMSL	11/11/05	< 0.00083	No	No	
ASBESTOS-ST1-11/11/05	030534149-0001	Southwest Area (street-level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST2-11/11/05	030534149-0002	Southeast Area (sidewalk bridge level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST4-11/11/05	030534149-0003	Northwest Area (street-level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST5-11/11/05	030534149-0004	Firehouse #10 (roof level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST10-11/11/05	030534149-0005	North Side Sidewalk Bridge	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST11-11/11/05	030534149-0006	90 Trinity Place (roof level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST12-11/11/05	030534149-0007	110 Greenwich Street (roof level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST13-11/11/05	030534149-0008	Marriott Hotel, 38th Floor (roof level)	11/11/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST1-11/12/05	030534150-0001	Southwest Area (street-level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST2-11/12/05	030534150-0002	Southeast Area (sidewalk bridge level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST4-11/12/05	030534150-0003	Northwest Area (street-level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST5-11/12/05	030534150-0004	Firehouse #10 (roof level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST10-11/12/05	030534150-0005	North Side Sidewalk Bridge	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST11-11/12/05	030534150-0006	90 Trinity Place (roof level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST12-11/12/05	030534150-0007	110 Greenwich Street (roof level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST13-11/12/05	030534150-0008	Marriott Hotel, 38th Floor (roof level)	11/12/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST1-11/13/05	030534151-0001	Southwest Area (street-level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST2-11/13/05	030534151-0002	Southeast Area (sidewalk bridge level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST4-11/13/05	030534151-0003	Northwest Area (street-level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST5-11/13/05	030534151-0004	Firehouse #10 (roof level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST10-11/13/05	030534151-0005	North Side Sidewalk Bridge	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST11-11/13/05	030534151-0006	90 Trinity Place (roof level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST12-11/13/05	030534151-0007	110 Greenwich Street (roof level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST13-11/13/05	030534151-0008	Marriott Hotel, 38th Floor (roof level)	11/13/05	1	2.970	Asbestos	PCME	EMSL	11/14/05	< 0.00083	No	No	
ASBESTOS-ST1-11/14/05	030534278-0001	Southwest Area (street-level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST2-11/14/05	030534278-0002	Southeast Area (sidewalk bridge level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST4-11/14/05	030534278-0003	Northwest Area (street-level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST5-11/14/05	030534278-0004	Firehouse #10 (roof level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST10-11/14/05	030534278-0005	North Side Sidewalk Bridge	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST11-11/14/05	030534278-0006	90 Trinity Place (roof level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST12-11/14/05	030534278-0007	110 Greenwich Street (roof level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	
ASBESTOS-ST13-11/14/05	030534278-0008	Marriott Hotel, 38th Floor (roof level)	11/14/05	1	2.970	Asbestos	PCME	EMSL	11/15/05	< 0.00083	No	No	