

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-11/08/06	030636586-0001	Southwest Area (sidewalk bridge level)	11/8/06	1	3.040	Asbestos	PCME	EMSL	11/9/06	< 0.00081	No	No	
ASBESTOS-ST2-11/08/06	030636586-0002	Southeast Area (sidewalk bridge level)	11/8/06	1	2.960	Asbestos	PCME	EMSL	11/9/06	< 0.00083	No	No	
ASBESTOS-ST4-11/08/06	030636586-0003	Northwest Area (street-level)	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST5-11/08/06	030636586-0004	Firehouse #10 (roof level)	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST10-11/08/06	030636586-0005	North Side Sidewalk Bridge	11/8/06	1	3.120	Asbestos	PCME	EMSL	11/9/06	< 0.00079	No	No	
ASBESTOS-ST100-11/08/06	030636586-0013	Station 10 Field Duplicate	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST11-11/08/06	030636586-0006	90 Trinity Place (roof level)	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST12-11/08/06	030636586-0007	110 Greenwich Street (roof level)	11/8/06	1	3.010	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST13-11/08/06	030636586-0008	Marriott Hotel, 38th Floor (roof level)	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST14-11/08/06	030636586-0009	West Face - South end at corner (scaffolding level)	11/8/06	1	2.960	Asbestos	PCME	EMSL	11/9/06	< 0.00083	No	No	
ASBESTOS-ST15-11/08/06	030636586-0010	South Face - East end at corner (scaffolding level)	11/8/06	1	3.010	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST16-11/08/06	030636586-0011	East Face - North end at corner (scaffolding level)	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST17-11/08/06	030636586-0012	North Face - West end at corner (scaffolding level)	11/8/06	1	3.020	Asbestos	PCME	EMSL	11/9/06	< 0.00082	No	No	
ASBESTOS-ST1-11/09/06	030636742-0001	Southwest Area (sidewalk bridge level)	11/9/06	1	3.020	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST2-11/09/06	030636742-0002	Southeast Area (sidewalk bridge level)	11/9/06	1	3.020	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST4-11/09/06	030636742-0003	Northwest Area (street-level)	11/9/06	1	2.990	Asbestos	PCME	EMSL	11/10/06	< 0.00083	No	No	
ASBESTOS-ST5-11/09/06	030636742-0004	Firehouse #10 (roof level)	11/9/06	1	3.010	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST10-11/09/06	030636742-0005	North Side Sidewalk Bridge	11/9/06	1	3.010	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST11-11/09/06	030636742-0006	90 Trinity Place (roof level)	11/9/06	1	3.020	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST12-11/09/06	030636742-0007	110 Greenwich Street (roof level)	11/9/06	1	2.990	Asbestos	PCME	EMSL	11/10/06	< 0.00083	No	No	
ASBESTOS-ST13-11/09/06	030636742-0008	Marriott Hotel, 38th Floor (roof level)	11/9/06	1	3.020	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST14-11/09/06	030636742-0009	West Face - South end at corner (scaffolding level)	11/9/06	1	3.040	Asbestos	PCME	EMSL	11/10/06	< 0.00081	No	No	
ASBESTOS-ST15-11/09/06	030636742-0010	South Face - East end at corner (scaffolding level)	11/9/06	1	3.010	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	
ASBESTOS-ST16-11/09/06	030636742-0011	East Face - North end at corner (scaffolding level)	11/9/06	1	2.970	Asbestos	PCME	EMSL	11/10/06	< 0.00083	No	No	
ASBESTOS-ST17-11/09/06	030636742-0012	North Face - West end at corner (scaffolding level)	11/9/06	1	3.020	Asbestos	PCME	EMSL	11/10/06	< 0.00082	No	No	