

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels											Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-11/10/06	030636982-0001	Southwest Area (sidewalk bridge level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST2-11/10/06	030636982-0002	Southeast Area (sidewalk bridge level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST4-11/10/06	030636982-0003	Northwest Area (street-level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST5-11/10/06	030636982-0004	Firehouse #10 (roof level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST10-11/10/06	030636982-0005	North Side Sidewalk Bridge	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST11-11/10/06	030636982-0006	90 Trinity Place (roof level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST12-11/10/06	030636982-0007	110 Greenwich Street (roof level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST13-11/10/06	030636982-0008	Marriott Hotel, 38th Floor (roof level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST14-11/10/06	030636982-0009	West Face - South end at corner (scaffolding level)	11/10/06	1	3.040	Asbestos	PCME	EMSL	11/13/06	< 0.00081	No	No	
ASBESTOS-ST15-11/10/06	030636982-0010	South Face - East end at corner (scaffolding level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST16-11/10/06	030636982-0011	East Face - North end at corner (scaffolding level)	11/10/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST17-11/10/06	030636982-0012	North Face - West end at corner (scaffolding level)	11/10/06	1	3.010	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST1-11/11/06	030636977-0001	Southwest Area (sidewalk bridge level)	11/11/06	1	3.040	Asbestos	PCME	EMSL	11/13/06	< 0.00081	No	No	
ASBESTOS-ST2-11/11/06	030636977-0002	Southeast Area (sidewalk bridge level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST4-11/11/06	030636977-0003	Northwest Area (street-level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST5-11/11/06	030636977-0004	Firehouse #10 (roof level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST10-11/11/06	030636977-0005	North Side Sidewalk Bridge	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST11-11/11/06	030636977-0006	90 Trinity Place (roof level)	11/11/06	1	3.040	Asbestos	PCME	EMSL	11/13/06	< 0.00081	No	No	
ASBESTOS-ST12-11/11/06	030636977-0007	110 Greenwich Street (roof level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST13-11/11/06	030636977-0008	Marriott Hotel, 38th Floor (roof level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST14-11/11/06	030636977-0009	West Face - South end at corner (scaffolding level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST15-11/11/06	030636977-0010	South Face - East end at corner (scaffolding level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST16-11/11/06	030636977-0011	East Face - North end at corner (scaffolding level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST17-11/11/06	030636977-0012	North Face - West end at corner (scaffolding level)	11/11/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST1-11/12/06	030636975-0001	Southwest Area (sidewalk bridge level)	11/12/06	1	2.980	Asbestos	PCME	EMSL	11/13/06	< 0.00083	No	No	
ASBESTOS-ST2-11/12/06	030636975-0002	Southeast Area (sidewalk bridge level)	11/12/06	1	3.190	Asbestos	PCME	EMSL	11/13/06	< 0.00077	No	No	
ASBESTOS-ST4-11/12/06	030636975-0003	Northwest Area (street-level)	11/12/06	1	3.010	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST5-11/12/06	030636975-0004	Firehouse #10 (roof level)	11/12/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST10-11/12/06	030636975-0005	North Side Sidewalk Bridge	11/12/06	1	3.060	Asbestos	PCME	EMSL	11/13/06	< 0.00081	No	No	
ASBESTOS-ST11-11/12/06	030636975-0006	90 Trinity Place (roof level)	11/12/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST12-11/12/06	030636975-0007	110 Greenwich Street (roof level)	11/12/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST13-11/12/06	030636975-0008	Marriott Hotel, 38th Floor (roof level)	11/12/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST14-11/12/06	030636975-0009	West Face - South end at corner (scaffolding level)	11/12/06	1	3.010	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST15-11/12/06	030636975-0010	South Face - East end at corner (scaffolding level)	11/12/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST16-11/12/06	030636975-0011	East Face - North end at corner (scaffolding level)	11/12/06	1	3.010	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST17-11/12/06	030636975-0012	North Face - West end at corner (scaffolding level)	11/12/06	1	3.020	Asbestos	PCME	EMSL	11/13/06	< 0.00082	No	No	
ASBESTOS-ST1-11/13/06	030637117-0001	Southwest Area (sidewalk bridge level)	11/13/06	1	3.000	Asbestos	PCME	EMSL	11/14/06	< 0.00082	No	No	
ASBESTOS-ST2-11/13/06	030637117-0002	Southeast Area (sidewalk bridge level)	11/13/06	1	3.170	Asbestos	PCME	EMSL	11/14/06	< 0.00078	No	No	
ASBESTOS-ST4-11/13/06	030637117-0003	Northwest Area (street-level)	11/13/06	1	2.980	Asbestos	PCME	EMSL	11/14/06	< 0.00083	No	No	
ASBESTOS-ST5-11/13/06	030637117-0004	Firehouse #10 (roof level)	11/13/06	1	3.020	Asbestos	PCME	EMSL	11/14/06	< 0.00082	No	No	
ASBESTOS-ST10-11/13/06	030637117-0005	North Side Sidewalk Bridge	11/13/06	1	2.990	Asbestos	PCME	EMSL	11/14/06	< 0.00083	No	No	
ASBESTOS-ST11-11/13/06	030637117-0006	90 Trinity Place (roof level)	11/13/06	1	3.030	Asbestos	PCME	EMSL	11/14/06	< 0.00081	No	No	
ASBESTOS-ST12-11/13/06	030637117-0007	110 Greenwich Street (roof level)	11/13/06	1	3.040	Asbestos	PCME	EMSL	11/14/06	< 0.00081	No	No	
ASBESTOS-ST13-11/13/06	030637117-0008	Marriott Hotel, 38th Floor (roof level)	11/13/06	1	3.020	Asbestos	PCME	EMSL	11/14/06	< 0.00082	No	No	
ASBESTOS-ST14-11/13/06	030637117-0009	West Face - South end at corner (scaffolding level)	11/13/06	1	3.030	Asbestos	PCME	EMSL	11/14/06	< 0.00081	No	No	
ASBESTOS-ST15-11/13/06	030637117-0010	South Face - East end at corner (scaffolding level)	11/13/06	1	3.020	Asbestos	PCME	EMSL	11/14/06	< 0.00082	No	No	
ASBESTOS-ST16-11/13/06	030637117-0011	East Face - North end at corner (scaffolding level)	11/13/06	1	3.020	Asbestos	PCME	EMSL	11/14/06	< 0.00082	No	No	
ASBESTOS-ST17-11/13/06	030637117-0012	North Face - West end at corner (scaffolding level)	11/13/06	1	3.040	Asbestos	PCME	EMSL	11/14/06	< 0.00081	No	No	