

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-11/15/08	030840853-0001	Southwest Area (sidewalk bridge level)	11/15/08	1	3.010	Asbestos	PCME	EMSL	11/17/08	< 0.00082	No	No	
ASBESTOS-ST2-11/15/08	030840853-0002	Southeast Area (sidewalk bridge level)	11/15/08	1	3.090	Asbestos	PCME	EMSL	11/17/08	< 0.00087	No	No	
ASBESTOS-ST4-11/15/08	030840853-0003	Northwest Area (street-level)	11/15/08	1	3.030	Asbestos	PCME	EMSL	11/17/08	< 0.00081	No	No	
ASBESTOS-ST5-11/15/08	030840853-0004	Firehouse #10 (roof level)	11/15/08	1	3.150	Asbestos	PCME	EMSL	11/17/08	< 0.00085	No	No	
ASBESTOS-ST10-11/15/08	030840853-0005	North Side Sidewalk Bridge	11/15/08	1	3.000	Asbestos	PCME	EMSL	11/17/08	< 0.00082	No	No	
ASBESTOS-ST11-11/15/08	030840853-0006	90 Trinity Place (roof level)	11/15/08	1	3.020	Asbestos	PCME	EMSL	11/17/08	< 0.00082	No	No	
ASBESTOS-ST12-11/15/08	030840853-0007	110 Greenwich Street (roof level)	11/15/08	1	3.040	Asbestos	PCME	EMSL	11/17/08	< 0.00081	No	No	
ASBESTOS-ST13-11/15/08	030840853-0008	Marriott Hotel, 38th Floor (roof level)	11/15/08	1	2.990	Asbestos	PCME	EMSL	11/17/08	< 0.00083	No	No	
ASBESTOS-ST14-11/15/08	030840853-0009	West Face - South end at corner (scaffolding level)	11/15/08	1	2.990	Asbestos	PCME	EMSL	11/17/08	< 0.00083	No	No	
ASBESTOS-ST15-11/15/08	030840853-0010	South Face - East end at corner (scaffolding level)	11/15/08	1	3.010	Asbestos	PCME	EMSL	11/17/08	< 0.00082	No	No	
ASBESTOS-ST16-11/15/08	030840853-0011	East Face - North end at corner (scaffolding level)	11/15/08	1	2.920	Asbestos	PCME	EMSL	11/17/08	< 0.00085	No	No	
ASBESTOS-ST17-11/15/08	030840853-0012	North Face - West end at corner (scaffolding level)	11/15/08	1	2.920	Asbestos	PCME	EMSL	11/17/08	< 0.00085	No	No	
ASBESTOS-ST1-11/16/08	030840852-0001	Southwest Area (sidewalk bridge level)	11/16/08	1	3.000	Asbestos	PCME	EMSL	11/17/08	< 0.00082	No	No	
ASBESTOS-ST2-11/16/08	030840852-0002	Southeast Area (sidewalk bridge level)	11/16/08	1	3.080	Asbestos	PCME	EMSL	11/17/08	< 0.00080	No	No	
ASBESTOS-ST4-11/16/08	030840852-0003	Northwest Area (street-level)	11/16/08	1	3.020	Asbestos	PCME	EMSL	11/17/08	< 0.00082	No	No	
ASBESTOS-ST5-11/16/08	030840852-0004	Firehouse #10 (roof level)	11/16/08	1	3.070	Asbestos	PCME	EMSL	11/17/08	< 0.00080	No	No	
ASBESTOS-ST10-11/16/08	030840852-0005	North Side Sidewalk Bridge	11/16/08	1	3.110	Asbestos	PCME	EMSL	11/17/08	< 0.00079	No	No	
ASBESTOS-ST11-11/16/08	030840852-0006	90 Trinity Place (roof level)	11/16/08	1	3.090	Asbestos	PCME	EMSL	11/17/08	< 0.00080	No	No	
ASBESTOS-ST12-11/16/08	030840852-0007	110 Greenwich Street (roof level)	11/16/08	1	3.090	Asbestos	PCME	EMSL	11/17/08	< 0.00080	No	No	
ASBESTOS-ST13-11/16/08	030840852-0008	Marriott Hotel, 38th Floor (roof level)	11/16/08	1	3.040	Asbestos	PCME	EMSL	11/17/08	< 0.00081	No	No	
ASBESTOS-ST14-11/16/08	030840852-0009	West Face - South end at corner (scaffolding level)	11/16/08	1	3.210	Asbestos	PCME	EMSL	11/17/08	< 0.00077	No	No	
ASBESTOS-ST15-11/16/08	030840852-0010	South Face - East end at corner (scaffolding level)	11/16/08	1	3.330	Asbestos	PCME	EMSL	11/17/08	< 0.00074	No	No	
ASBESTOS-ST16-11/16/08	030840852-0011	East Face - North end at corner (scaffolding level)	11/16/08	1	3.200	Asbestos	PCME	EMSL	11/17/08	< 0.00077	No	No	
ASBESTOS-ST17-11/16/08	030840852-0012	North Face - West end at corner (scaffolding level)	11/16/08	1	3.270	Asbestos	PCME	EMSL	11/17/08	< 0.00075	No	No	