

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-11/17/08	030840978-0001	Southwest Area (sidewalk bridge level)	11/17/08	1	3.110	Asbestos	PCME	EMSL	11/18/08	< 0.00087	No	No	
ASBESTOS-ST2-11/17/08	030840978-0002	Southeast Area (sidewalk bridge level)	11/17/08	1	3.010	Asbestos	PCME	EMSL	11/18/08	< 0.00082	No	No	
ASBESTOS-ST4-11/17/08	030840978-0003	Northwest Area (street-level)	11/17/08	1	3.040	Asbestos	PCME	EMSL	11/18/08	< 0.00081	No	No	
ASBESTOS-ST5-11/17/08	030840978-0004	Firehouse #10 (roof level)	11/17/08	1	3.000	Asbestos	PCME	EMSL	11/18/08	< 0.00082	No	No	
ASBESTOS-ST10-11/17/08	030840978-0005	North Side Sidewalk Bridge	11/17/08	1	3.010	Asbestos	PCME	EMSL	11/18/08	< 0.00082	No	No	
ASBESTOS-ST11-11/17/08	030840978-0006	90 Trinity Place (roof level)	11/17/08	1	3.030	Asbestos	PCME	EMSL	11/18/08	< 0.00081	No	No	
ASBESTOS-ST12-11/17/08	030840978-0007	110 Greenwich Street (roof level)	11/17/08	1	3.070	Asbestos	PCME	EMSL	11/18/08	< 0.00080	No	No	
ASBESTOS-ST13-11/17/08	030840978-0008	Marriott Hotel, 38th Floor (roof level)	11/17/08	1	3.050	Asbestos	PCME	EMSL	11/18/08	< 0.00081	No	No	
ASBESTOS-ST14-11/17/08	030840978-0009	West Face - South end at corner (scaffolding level)	11/17/08	1	2.960	Asbestos	PCME	EMSL	11/18/08	< 0.00083	No	No	
ASBESTOS-ST15-11/17/08	030840978-0010	South Face - East end at corner (scaffolding level)	11/17/08	1	3.050	Asbestos	PCME	EMSL	11/18/08	< 0.00081	No	No	
ASBESTOS-ST16-11/17/08	030840978-0011	East Face - North end at corner (scaffolding level)	11/17/08	1	3.050	Asbestos	PCME	EMSL	11/18/08	< 0.00081	No	No	
ASBESTOS-ST17-11/17/08	030840978-0012	North Face - West end at corner (scaffolding level)	11/17/08	1	3.030	Asbestos	PCME	EMSL	11/18/08	< 0.00081	No	No	
ASBESTOS-ST1-11/18/08	030841121-0001	Southwest Area (sidewalk bridge level)	11/18/08	1	3.030	Asbestos	PCME	EMSL	11/19/08	< 0.00081	No	No	
ASBESTOS-ST2-11/18/08	030841121-0002	Southeast Area (sidewalk bridge level)	11/18/08	1	3.000	Asbestos	PCME	EMSL	11/19/08	< 0.00082	No	No	
ASBESTOS-ST4-11/18/08	030841121-0003	Northwest Area (street-level)	11/18/08	1	3.060	Asbestos	PCME	EMSL	11/19/08	< 0.00081	No	No	
ASBESTOS-ST5-11/18/08	030841121-0004	Firehouse #10 (roof level)	11/18/08	1	3.080	Asbestos	PCME	EMSL	11/19/08	< 0.00080	No	No	
ASBESTOS-ST10-11/18/08	030841121-0005	North Side Sidewalk Bridge	11/18/08	1	2.980	Asbestos	PCME	EMSL	11/19/08	< 0.00083	No	No	
ASBESTOS-ST11-11/18/08	030841121-0006	90 Trinity Place (roof level)	11/18/08	1	2.980	Asbestos	PCME	EMSL	11/19/08	< 0.00083	No	No	
ASBESTOS-ST12-11/18/08	030841121-0007	110 Greenwich Street (roof level)	11/18/08	1	2.990	Asbestos	PCME	EMSL	11/19/08	< 0.00083	No	No	
ASBESTOS-ST13-11/18/08	030841121-0008	Marriott Hotel, 38th Floor (roof level)	11/18/08	1	3.060	Asbestos	PCME	EMSL	11/19/08	< 0.00081	No	No	
ASBESTOS-ST14-11/18/08	030841121-0009	West Face - South end at corner (scaffolding level)	11/18/08	1	2.990	Asbestos	PCME	EMSL	11/19/08	< 0.00083	No	No	
ASBESTOS-ST15-11/18/08	030841121-0010	South Face - East end at corner (scaffolding level)	11/18/08	1	3.030	Asbestos	PCME	EMSL	11/19/08	< 0.00081	No	No	
ASBESTOS-ST16-11/18/08	030841121-0011	East Face - North end at corner (scaffolding level)	11/18/08	1	3.000	Asbestos	PCME	EMSL	11/19/08	< 0.00082	No	No	
ASBESTOS-ST17-11/18/08	030841121-0012	North Face - West end at corner (scaffolding level)	11/18/08	1	3.040	Asbestos	PCME	EMSL	11/19/08	< 0.00081	No	No	
ASBESTOS-ST1-11/19/08	030841237-0001	Southwest Area (sidewalk bridge level)	11/19/08	1	2.970	Asbestos	PCME	EMSL	11/20/08	< 0.00083	No	No	
ASBESTOS-ST2-11/19/08	030841237-0002	Southeast Area (sidewalk bridge level)	11/19/08	1	3.120	Asbestos	PCME	EMSL	11/20/08	< 0.00079	No	No	
ASBESTOS-ST4-11/19/08	030841237-0003	Northwest Area (street-level)	11/19/08	1	3.060	Asbestos	PCME	EMSL	11/20/08	< 0.00081	No	No	
ASBESTOS-ST5-11/19/08	030841237-0004	Firehouse #10 (roof level)	11/19/08	1	3.020	Asbestos	PCME	EMSL	11/20/08	< 0.00082	No	No	
ASBESTOS-ST10-11/19/08	030841237-0005	North Side Sidewalk Bridge	11/19/08	1	3.030	Asbestos	PCME	EMSL	11/20/08	< 0.00081	No	No	
ASBESTOS-ST11-11/19/08	030841237-0006	90 Trinity Place (roof level)	11/19/08	1	3.020	Asbestos	PCME	EMSL	11/20/08	< 0.00082	No	No	
ASBESTOS-ST12-11/19/08	030841237-0007	110 Greenwich Street (roof level)	11/19/08	1	3.070	Asbestos	PCME	EMSL	11/20/08	< 0.00080	No	No	
ASBESTOS-ST13-11/19/08	030841237-0008	Marriott Hotel, 38th Floor (roof level)	11/19/08	1	3.030	Asbestos	PCME	EMSL	11/20/08	< 0.00081	No	No	
ASBESTOS-ST14-11/19/08	030841237-0009	West Face - South end at corner (scaffolding level)	11/19/08	1	3.120	Asbestos	PCME	EMSL	11/20/08	< 0.00079	No	No	
ASBESTOS-ST15-11/19/08	030841237-0010	South Face - East end at corner (scaffolding level)	11/19/08	1	3.050	Asbestos	PCME	EMSL	11/20/08	< 0.00081	No	No	
ASBESTOS-ST16-11/19/08	030841237-0011	East Face - North end at corner (scaffolding level)	11/19/08	1	3.100	Asbestos	PCME	EMSL	11/20/08	< 0.00080	No	No	
ASBESTOS-ST17-11/19/08	030841237-0012	North Face - West end at corner (scaffolding level)	11/19/08	1	3.090	Asbestos	PCME	EMSL	11/20/08	< 0.00080	No	No	