

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-11/26/05	030535578-0001	Southwest Area (sidewalk bridge level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST2-11/26/05	030535578-0002	Southeast Area (sidewalk bridge level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST4-11/26/05	030535578-0003	Northwest Area (street-level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST5-11/26/05	030535578-0004	Firehouse #10 (roof level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST10-11/26/05	030535578-0005	North Side Sidewalk Bridge	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST11-11/26/05	030535578-0006	90 Trinity Place (roof level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST12-11/26/05	030535578-0007	110 Greenwich Street (roof level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST13-11/26/05	030535578-0008	Marriott Hotel, 38th Floor (roof level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST14-11/26/05	030535578-0009	West Face - South end at corner (scaffolding level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST15-11/26/05	030535578-0010	South Face - East end at corner (scaffolding level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST16-11/26/05	030535578-0011	East Face - North end at corner (scaffolding level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST17-11/26/05	030535578-0012	North Face - West end at corner (scaffolding level)	11/26/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST1-11/27/05	030535573-0001	Southwest Area (sidewalk bridge level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST2-11/27/05	030535573-0002	Southeast Area (sidewalk bridge level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST4-11/27/05	030535573-0003	Northwest Area (street-level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST5-11/27/05	030535573-0004	Firehouse #10 (roof level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST10-11/27/05	030535573-0005	North Side Sidewalk Bridge	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST11-11/27/05	030535573-0006	90 Trinity Place (roof level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST12-11/27/05	030535573-0007	110 Greenwich Street (roof level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST13-11/27/05	030535573-0008	Marriott Hotel, 38th Floor (roof level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST14-11/27/05	030535573-0009	West Face - South end at corner (scaffolding level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST15-11/27/05	030535573-0010	South Face - East end at corner (scaffolding level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST16-11/27/05	030535573-0011	East Face - North end at corner (scaffolding level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST17-11/27/05	030535573-0012	North Face - West end at corner (scaffolding level)	11/27/05	1	2.970	Asbestos	PCME	EMSL	11/28/05	< 0.00083	No	No	
ASBESTOS-ST1-11/28/05	030535664-0001	Southwest Area (sidewalk bridge level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST2-11/28/05	030535664-0002	Southeast Area (sidewalk bridge level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST4-11/28/05	030535664-0003	Northwest Area (street-level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST5-11/28/05	030535664-0004	Firehouse #10 (roof level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST10-11/28/05	030535664-0005	North Side Sidewalk Bridge	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST100-11/28/05	030535664-0013	Station 10 Field Duplicate	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST11-11/28/05	030535664-0006	90 Trinity Place (roof level)	11/28/05	1	3.670	Asbestos	PCME	EMSL	11/29/05	< 0.00067	No	No	
ASBESTOS-ST12-11/28/05	030535664-0007	110 Greenwich Street (roof level)	11/28/05	1	3.510	Asbestos	PCME	EMSL	11/29/05	< 0.00070	No	No	
ASBESTOS-ST13-11/28/05	030535664-0008	Marriott Hotel, 38th Floor (roof level)	11/28/05	1	3.590	Asbestos	PCME	EMSL	11/29/05	< 0.00069	No	No	
ASBESTOS-ST14-11/28/05	030535664-0009	West Face - South end at corner (scaffolding level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST15-11/28/05	030535664-0010	South Face - East end at corner (scaffolding level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST16-11/28/05	030535664-0011	East Face - North end at corner (scaffolding level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST17-11/28/05	030535664-0012	North Face - West end at corner (scaffolding level)	11/28/05	1	2.970	Asbestos	PCME	EMSL	11/29/05	< 0.00083	No	No	
ASBESTOS-ST1-11/29/05	030535810-0001	Southwest Area (sidewalk bridge level)	11/29/05	1	3.010	Asbestos	PCME	EMSL	11/30/05	< 0.00082	No	No	
ASBESTOS-ST2-11/29/05	030535810-0002	Southeast Area (sidewalk bridge level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST4-11/29/05	030535810-0003	Northwest Area (street-level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST5-11/29/05	030535810-0004	Firehouse #10 (roof level)	11/29/05	1	2.780	Asbestos	PCME	EMSL	11/30/05	< 0.00089	No	No	
ASBESTOS-ST10-11/29/05	030535810-0005	North Side Sidewalk Bridge	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST11-11/29/05	030535810-0006	90 Trinity Place (roof level)	11/29/05	1	2.920	Asbestos	PCME	EMSL	11/30/05	< 0.00085	No	No	
ASBESTOS-ST12-11/29/05	030535810-0007	110 Greenwich Street (roof level)	11/29/05	1	2.940	Asbestos	PCME	EMSL	11/30/05	< 0.00084	No	No	
ASBESTOS-ST13-11/29/05	030535810-0008	Marriott Hotel, 38th Floor (roof level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST14-11/29/05	030535810-0009	West Face - South end at corner (scaffolding level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST15-11/29/05	030535810-0010	South Face - East end at corner (scaffolding level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST16-11/29/05	030535810-0011	East Face - North end at corner (scaffolding level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	
ASBESTOS-ST17-11/29/05	030535810-0012	North Face - West end at corner (scaffolding level)	11/29/05	1	2.970	Asbestos	PCME	EMSL	11/30/05	< 0.00083	No	No	