

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-12/2/05	030536339-0001	Southwest Area (sidewalk bridge level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST2-12/2/05	030536339-0002	Southeast Area (sidewalk bridge level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST4-12/2/05	030536339-0003	Northwest Area (street-level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST5-12/2/05	030536339-0004	Firehouse #10 (roof level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST10-12/2/05	030536339-0005	North Side Sidewalk Bridge	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST11-12/2/05	030536339-0006	90 Trinity Place (roof level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST12-12/2/05	030536339-0007	110 Greenwich Street (roof level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST13-12/2/05	030536339-0008	Marriott Hotel, 38th Floor (roof level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST14-12/2/05	030536339-0009	West Face - South end at corner (scaffolding level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST15-12/2/05	030536339-0010	South Face - East end at corner (scaffolding level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST16-12/2/05	030536339-0011	East Face - North end at corner (scaffolding level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST17-12/2/05	030536339-0012	North Face - West end at corner (scaffolding level)	12/2/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST1-12/3/05	030536340-0001	Southwest Area (sidewalk bridge level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST2-12/3/05	030536340-0002	Southeast Area (sidewalk bridge level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST4-12/3/05	030536340-0003	Northwest Area (street-level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST5-12/3/05	030536340-0004	Firehouse #10 (roof level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST10-12/3/05	030536340-0005	North Side Sidewalk Bridge	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST11-12/3/05	030536340-0006	90 Trinity Place (roof level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST12-12/3/05	030536340-0007	110 Greenwich Street (roof level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST13-12/3/05	030536340-0008	Marriott Hotel, 38th Floor (roof level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST14-12/3/05	030536340-0009	West Face - South end at corner (scaffolding level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST15-12/3/05	030536340-0010	South Face - East end at corner (scaffolding level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST16-12/3/05	030536340-0011	East Face - North end at corner (scaffolding level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST17-12/3/05	030536340-0012	North Face - West end at corner (scaffolding level)	12/3/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST1-12/4/05	030536341-0001	Southwest Area (sidewalk bridge level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST2-12/4/05	030536341-0002	Southeast Area (sidewalk bridge level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST4-12/4/05	030536341-0003	Northwest Area (street-level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST5-12/4/05	030536341-0004	Firehouse #10 (roof level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST10-12/4/05	030536341-0005	North Side Sidewalk Bridge	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST11-12/4/05	030536341-0006	90 Trinity Place (roof level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST12-12/4/05	030536341-0007	110 Greenwich Street (roof level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST13-12/4/05	030536341-0008	Marriott Hotel, 38th Floor (roof level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST14-12/4/05	030536341-0009	West Face - South end at corner (scaffolding level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST15-12/4/05	030536341-0010	South Face - East end at corner (scaffolding level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST16-12/4/05	030536341-0011	East Face - North end at corner (scaffolding level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST17-12/4/05	030536341-0012	North Face - West end at corner (scaffolding level)	12/4/05	1	2.970	Asbestos	PCME	EMSL	12/5/05	< 0.00083	No	No	
ASBESTOS-ST1-12/5/05	030536482-0001	Southwest Area (sidewalk bridge level)	12/5/05	1	2.700	Asbestos	PCME	EMSL	12/6/05	< 0.00084	No	No	
ASBESTOS-ST2-12/5/05	030536482-0002	Southeast Area (sidewalk bridge level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST4-12/5/05	030536482-0003	Northwest Area (street-level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST5-12/5/05	030536482-0004	Firehouse #10 (roof level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST10-12/5/05	030536482-0005	North Side Sidewalk Bridge	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST11-12/5/05	030536482-0006	90 Trinity Place (roof level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST12-12/5/05	030536482-0007	110 Greenwich Street (roof level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST13-12/5/05	030536482-0008	Marriott Hotel, 38th Floor (roof level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST14-12/5/05	030536482-0009	West Face - South end at corner (scaffolding level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST15-12/5/05	030536482-0010	South Face - East end at corner (scaffolding level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST16-12/5/05	030536482-0011	East Face - North end at corner (scaffolding level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST17-12/5/05	030536482-0012	North Face - West end at corner (scaffolding level)	12/5/05	1	2.970	Asbestos	PCME	EMSL	12/6/05	< 0.00083	No	No	
ASBESTOS-ST1-12/6/05	030536613-0001	Southwest Area (sidewalk bridge level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST2-12/6/05	030536613-0002	Southeast Area (sidewalk bridge level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST4-12/6/05	030536613-0003	Northwest Area (street-level)	12/6/05	1	3.130	Asbestos	PCME	EMSL	12/7/05	< 0.00086	No	No	
ASBESTOS-ST5-12/6/05	030536613-0004	Firehouse #10 (roof level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST10-12/6/05	030536613-0005	North Side Sidewalk Bridge	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST100-12/6/05	030536613-0013	Station 10 Field Duplicate	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST11-12/6/05	030536613-0006	90 Trinity Place (roof level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST12-12/6/05	030536613-0007	110 Greenwich Street (roof level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST13-12/6/05	030536613-0008	Marriott Hotel, 38th Floor (roof level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST14-12/6/05	030536613-0009	West Face - South end at corner (scaffolding level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST15-12/6/05	030536613-0010	South Face - East end at corner (scaffolding level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST16-12/6/05	030536613-0011	East Face - North end at corner (scaffolding level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	
ASBESTOS-ST17-12/6/05	030536613-0012	North Face - West end at corner (scaffolding level)	12/6/05	1	2.970	Asbestos	PCME	EMSL	12/7/05	< 0.00083	No	No	