

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target | Exceeds EPA | Comments |
|-------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|---|--------------------|------------------------------|----------|
| | | | | | | | | | | 0.0009 | Air Quality Levels | Site Specific Trigger Levels | |
| | | | | | | | | | | NA | | | |
| | | | | | | | | | | Target Air Quality Levels | | | |
| | | | | | | | | | | EPA Site Specific Trigger Levels | | | |
| ASBESTOS-ST1-12/12/06 | 030640146-0001 | Southwest Area (sidewalk bridge level) | 12/12/06 | 1 | 3.100 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00080 | No | No | |
| ASBESTOS-ST2-12/12/06 | 030640146-0002 | Southeast Area (sidewalk bridge level) | 12/12/06 | 1 | 3.100 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00080 | No | No | |
| ASBESTOS-ST4-12/12/06 | 030640146-0003 | Northwest Area (street-level) | 12/12/06 | 1 | 3.170 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00078 | No | No | |
| ASBESTOS-ST5-12/12/06 | 030640146-0004 | Firehouse #10 (roof level) | 12/12/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00081 | No | No | |
| ASBESTOS-ST10-12/12/06 | 030640146-0005 | North Side Sidewalk Bridge | 12/12/06 | 1 | 3.130 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00079 | No | No | |
| ASBESTOS-ST100-12/12/06 | 030640146-0013 | Station 10 Field Duplicate | 12/12/06 | 1 | 3.230 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00083 | No | No | |
| ASBESTOS-ST11-12/12/06 | 030640146-0006 | 90 Trinity Place (roof level) | 12/12/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00081 | No | No | |
| ASBESTOS-ST12-12/12/06 | 030640146-0007 | 110 Greenwich Street (roof level) | 12/12/06 | 1 | 3.060 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00081 | No | No | |
| ASBESTOS-ST13-12/12/06 | 030640146-0008 | Marriott Hotel, 38th Floor (roof level) | 12/12/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00081 | No | No | |
| ASBESTOS-ST14-12/12/06 | 030640146-0009 | West Face - South end at corner (scaffolding level) | 12/12/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00081 | No | No | |
| ASBESTOS-ST15-12/12/06 | 030640146-0010 | South Face - East end at corner (scaffolding level) | 12/12/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00082 | No | No | |
| ASBESTOS-ST16-12/12/06 | 030640146-0011 | East Face - North end at corner (scaffolding level) | 12/12/06 | 1 | 3.010 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00082 | No | No | |
| ASBESTOS-ST17-12/12/06 | 030640146-0012 | North Face - West end at corner (scaffolding level) | 12/12/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 12/13/06 | < 0.00081 | No | No | |
| ASBESTOS-ST1-12/13/06 | 030640291-0001 | Southwest Area (sidewalk bridge level) | 12/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00082 | No | No | |
| ASBESTOS-ST2-12/13/06 | 030640291-0002 | Southeast Area (sidewalk bridge level) | 12/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00082 | No | No | |
| ASBESTOS-ST4-12/13/06 | 030640291-0003 | Northwest Area (street-level) | 12/13/06 | 1 | 2.990 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00083 | No | No | |
| ASBESTOS-ST5-12/13/06 | 030640291-0004 | Firehouse #10 (roof level) | 12/13/06 | 1 | 3.200 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00077 | No | No | |
| ASBESTOS-ST10-12/13/06 | 030640291-0005 | North Side Sidewalk Bridge | 12/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00082 | No | No | |
| ASBESTOS-ST11-12/13/06 | 030640291-0006 | 90 Trinity Place (roof level) | 12/13/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00084 | No | No | |
| ASBESTOS-ST12-12/13/06 | 030640291-0007 | 110 Greenwich Street (roof level) | 12/13/06 | 1 | 3.040 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00081 | No | No | |
| ASBESTOS-ST13-12/13/06 | 030640291-0008 | Marriott Hotel, 38th Floor (roof level) | 12/13/06 | 1 | 2.850 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00087 | No | No | |
| ASBESTOS-ST14-12/13/06 | 030640291-0009 | West Face - South end at corner (scaffolding level) | 12/13/06 | 1 | 3.130 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00079 | No | No | |
| ASBESTOS-ST15-12/13/06 | 030640291-0010 | South Face - East end at corner (scaffolding level) | 12/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00082 | No | No | |
| ASBESTOS-ST16-12/13/06 | 030640291-0011 | East Face - North end at corner (scaffolding level) | 12/13/06 | 1 | 3.020 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00082 | No | No | |
| ASBESTOS-ST17-12/13/06 | 030640291-0012 | North Face - West end at corner (scaffolding level) | 12/13/06 | 1 | 3.090 | Asbestos | PCME | EMSL | 12/14/06 | < 0.00080 | No | No | |