

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-12/20/07	030739533-0001	Southwest Area (sidewalk bridge level)	12/20/07	1	2.990	Asbestos	PCME	EMSL	12/21/07	< 0.00083	No	No	
ASBESTOS-ST2-12/20/07	030739533-0002	Southeast Area (sidewalk bridge level)	12/20/07	1	3.040	Asbestos	PCME	EMSL	12/21/07	< 0.00081	No	No	
ASBESTOS-ST4-12/20/07	030739533-0003	Northwest Area (street-level)	12/20/07	1	3.050	Asbestos	PCME	EMSL	12/21/07	< 0.00081	No	No	
ASBESTOS-ST5-12/20/07	030739533-0004	Firehouse #10 (roof level)	12/20/07	1	3.040	Asbestos	PCME	EMSL	12/21/07	< 0.00081	No	No	
ASBESTOS-ST10-12/20/07	030739533-0005	North Side Sidewalk Bridge	12/20/07	1	3.010	Asbestos	PCME	EMSL	12/21/07	< 0.00082	No	No	
ASBESTOS-ST11-12/20/07	030739533-0006	90 Trinity Place (roof level)	12/20/07	1	3.040	Asbestos	PCME	EMSL	12/21/07	< 0.00081	No	No	
ASBESTOS-ST12-12/20/07	030739533-0007	110 Greenwich Street (roof level)	12/20/07	1	3.040	Asbestos	PCME	EMSL	12/21/07	< 0.00081	No	No	
ASBESTOS-ST13-12/20/07	030739533-0008	Marriott Hotel, 38th Floor (roof level)	12/20/07	1	2.990	Asbestos	PCME	EMSL	12/21/07	< 0.00083	No	No	
ASBESTOS-ST14-12/20/07	030739533-0009	West Face - South end at corner (scaffolding level)	12/20/07	1	3.040	Asbestos	PCME	EMSL	12/21/07	< 0.00081	No	No	
ASBESTOS-ST15-12/20/07	030739533-0010	South Face - East end at corner (scaffolding level)	12/20/07	1	3.000	Asbestos	PCME	EMSL	12/21/07	< 0.00082	No	No	
ASBESTOS-ST16-12/20/07	030739533-0011	East Face - North end at corner (scaffolding level)	12/20/07	1	3.000	Asbestos	PCME	EMSL	12/21/07	< 0.00082	No	No	
ASBESTOS-ST17-12/20/07	030739533-0012	North Face - West end at corner (scaffolding level)	12/20/07	1	3.010	Asbestos	PCME	EMSL	12/21/07	< 0.00082	No	No	
ASBESTOS-ST1-12/21/07	030739754-0001	Southwest Area (sidewalk bridge level)	12/21/07	1	3.050	Asbestos	PCME	EMSL	12/24/07	< 0.00088	No	No	
ASBESTOS-ST2-12/21/07	030739754-0002	Southeast Area (sidewalk bridge level)	12/21/07	1	3.010	Asbestos	PCME	EMSL	12/24/07	< 0.00089	No	No	
ASBESTOS-ST4-12/21/07	030739754-0003	Northwest Area (street-level)	12/21/07	1	3.000	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST5-12/21/07	030739754-0004	Firehouse #10 (roof level)	12/21/07	1	3.100	Asbestos	PCME	EMSL	12/24/07	< 0.00087	No	No	
ASBESTOS-ST10-12/21/07	030739754-0005	North Side Sidewalk Bridge	12/21/07	1	3.030	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST11-12/21/07	030739754-0006	90 Trinity Place (roof level)	12/21/07	1	3.010	Asbestos	PCME	EMSL	12/24/07	< 0.00089	No	No	
ASBESTOS-ST12-12/21/07	030739754-0007	110 Greenwich Street (roof level)	12/21/07	1	3.060	Asbestos	PCME	EMSL	12/24/07	< 0.00088	No	No	
ASBESTOS-ST13-12/21/07	030739754-0008	Marriott Hotel, 38th Floor (roof level)	12/21/07	1	3.050	Asbestos	PCME	EMSL	12/24/07	< 0.00088	No	No	
ASBESTOS-ST14-12/21/07	030739754-0009	West Face - South end at corner (scaffolding level)	12/21/07	1	2.970	Asbestos	PCME	EMSL	12/24/07	< 0.00083	No	No	
ASBESTOS-ST15-12/21/07	030739754-0010	South Face - East end at corner (scaffolding level)	12/21/07	1	3.040	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST16-12/21/07	030739754-0011	East Face - North end at corner (scaffolding level)	12/21/07	1	3.060	Asbestos	PCME	EMSL	12/24/07	< 0.00088	No	No	
ASBESTOS-ST17-12/21/07	030739754-0012	North Face - West end at corner (scaffolding level)	12/21/07	1	3.150	Asbestos	PCME	EMSL	12/24/07	< 0.00085	No	No	
ASBESTOS-ST1-12/22/07	030739757-0001	Southwest Area (sidewalk bridge level)	12/22/07	1	2.990	Asbestos	PCME	EMSL	12/24/07	< 0.00083	No	No	
ASBESTOS-ST2-12/22/07	030739757-0002	Southeast Area (sidewalk bridge level)	12/22/07	1	3.040	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST4-12/22/07	030739757-0003	Northwest Area (street-level)	12/22/07	1	3.060	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST5-12/22/07	030739757-0004	Firehouse #10 (roof level)	12/22/07	1	3.040	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST10-12/22/07	030739757-0005	North Side Sidewalk Bridge	12/22/07	1	3.120	Asbestos	PCME	EMSL	12/24/07	< 0.00079	No	No	
ASBESTOS-ST11-12/22/07	030739757-0006	90 Trinity Place (roof level)	12/22/07	1	3.020	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST12-12/22/07	030739757-0007	110 Greenwich Street (roof level)	12/22/07	1	2.990	Asbestos	PCME	EMSL	12/24/07	< 0.00083	No	No	
ASBESTOS-ST13-12/22/07	030739757-0008	Marriott Hotel, 38th Floor (roof level)	12/22/07	1	3.010	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST14-12/22/07	030739757-0009	West Face - South end at corner (scaffolding level)	12/22/07	1	3.020	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST15-12/22/07	030739757-0010	South Face - East end at corner (scaffolding level)	12/22/07	1	3.030	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST16-12/22/07	030739757-0011	East Face - North end at corner (scaffolding level)	12/22/07	1	3.010	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST17-12/22/07	030739757-0012	North Face - West end at corner (scaffolding level)	12/22/07	1	3.020	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST1-12/23/07	030739756-0001	Southwest Area (sidewalk bridge level)	12/23/07	1	3.240	Asbestos	PCME	EMSL	12/24/07	< 0.00076	No	No	
ASBESTOS-ST2-12/23/07	030739756-0002	Southeast Area (sidewalk bridge level)	12/23/07	1	3.130	Asbestos	PCME	EMSL	12/24/07	< 0.00079	No	No	
ASBESTOS-ST4-12/23/07	030739756-0003	Northwest Area (street-level)	12/23/07	1	3.140	Asbestos	PCME	EMSL	12/24/07	< 0.00079	No	No	
ASBESTOS-ST5-12/23/07	030739756-0004	Firehouse #10 (roof level)	12/23/07	1	2.970	Asbestos	PCME	EMSL	12/24/07	< 0.00083	No	No	
ASBESTOS-ST10-12/23/07	030739756-0005	North Side Sidewalk Bridge	12/23/07	1	3.010	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST11-12/23/07	030739756-0006	90 Trinity Place (roof level)	12/23/07	1	3.040	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST12-12/23/07	030739756-0007	110 Greenwich Street (roof level)	12/23/07	1	3.000	Asbestos	PCME	EMSL	12/24/07	< 0.00082	No	No	
ASBESTOS-ST13-12/23/07	030739756-0008	Marriott Hotel, 38th Floor (roof level)	12/23/07	1	2.950	Asbestos	PCME	EMSL	12/24/07	< 0.00084	No	No	
ASBESTOS-ST14-12/23/07	030739756-0009	West Face - South end at corner (scaffolding level)	12/23/07	1	3.150	Asbestos	PCME	EMSL	12/24/07	< 0.00078	No	No	
ASBESTOS-ST15-12/23/07	030739756-0010	South Face - East end at corner (scaffolding level)	12/23/07	1	2.990	Asbestos	PCME	EMSL	12/24/07	< 0.00083	No	No	
ASBESTOS-ST16-12/23/07	030739756-0011	East Face - North end at corner (scaffolding level)	12/23/07	1	3.040	Asbestos	PCME	EMSL	12/24/07	< 0.00081	No	No	
ASBESTOS-ST1-12/24/07	030739793-0001	Southwest Area (sidewalk bridge level)	12/24/07	1	3.040	Asbestos	PCME	EMSL	12/26/07	< 0.00089	No	No	
ASBESTOS-ST2-12/24/07	030739793-0002	Southeast Area (sidewalk bridge level)	12/24/07	1	3.120	Asbestos	PCME	EMSL	12/26/07	< 0.00086	No	No	
ASBESTOS-ST4-12/24/07	030739793-0003	Northwest Area (street-level)	12/24/07	1	3.070	Asbestos	PCME	EMSL	12/26/07	< 0.00088	No	No	
ASBESTOS-ST5-12/24/07	030739793-0004	Firehouse #10 (roof level)	12/24/07	1	2.970	Asbestos	PCME	EMSL	12/26/07	< 0.00083	No	No	
ASBESTOS-ST10-12/24/07	030739793-0005	North Side Sidewalk Bridge	12/24/07	1	3.140	Asbestos	PCME	EMSL	12/26/07	< 0.00086	No	No	
ASBESTOS-ST11-12/24/07	030739793-0006	90 Trinity Place (roof level)	12/24/07	1	3.080	Asbestos	PCME	EMSL	12/26/07	< 0.00087	No	No	
ASBESTOS-ST12-12/24/07	030739793-0007	110 Greenwich Street (roof level)	12/24/07	1	3.040	Asbestos	PCME	EMSL	12/26/07	< 0.00089	No	No	
ASBESTOS-ST13-12/24/07	030739793-0008	Marriott Hotel, 38th Floor (roof level)	12/24/07	1	3.010	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST14-12/24/07	030739793-0009	West Face - South end at corner (scaffolding level)	12/24/07	1	3.020	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST15-12/24/07	030739793-0010	South Face - East end at corner (scaffolding level)	12/24/07	1	3.070	Asbestos	PCME	EMSL	12/26/07	< 0.00080	No	No	
ASBESTOS-ST16-12/24/07	030739793-0011	East Face - North end at corner (scaffolding level)	12/24/07	1	2.990	Asbestos	PCME	EMSL	12/26/07	< 0.00083	No	No	
ASBESTOS-ST17-12/24/07	030739793-0012	North Face - West end at corner (scaffolding level)	12/24/07	1	2.500	Asbestos	PCME	EMSL	12/26/07	< 0.00074	No	No	
ASBESTOS-ST1-12/25/07	030739789-0001	Southwest Area (sidewalk bridge level)	12/25/07	1	2.980	Asbestos	PCME	EMSL	12/26/07	< 0.00083	No	No	
ASBESTOS-ST2-12/25/07	030739789-0002	Southeast Area (sidewalk bridge level)	12/25/07	1	2.970	Asbestos	PCME	EMSL	12/26/07	< 0.00083	No	No	
ASBESTOS-ST4-12/25/07	030739789-0003	Northwest Area (street-level)	12/25/07	1	3.020	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST5-12/25/07	030739789-0004	Firehouse #10 (roof level)	12/25/07	1	3.000	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST10-12/25/07	030739789-0005	North Side Sidewalk Bridge	12/25/07	1	3.030	Asbestos	PCME	EMSL	12/26/07	< 0.00081	No	No	
ASBESTOS-ST11-12/25/07	030739789-0006	90 Trinity Place (roof level)	12/25/07	1	3.000	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST12-12/25/07	030739789-0007	110 Greenwich Street (roof level)	12/25/07	1	3.060	Asbestos	PCME	EMSL	12/26/07	< 0.00081	No	No	
ASBESTOS-ST13-12/25/07	030739789-0008	Marriott Hotel, 38th Floor (roof level)	12/25/07	1	3.040	Asbestos	PCME	EMSL	12/26/07	< 0.00081	No	No	
ASBESTOS-ST14-12/25/07	030739789-0009	West Face - South end at corner (scaffolding level)	12/25/07	1	3.020	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST15-12/25/07	030739789-0010	South Face - East end at corner (scaffolding level)	12/25/07	1	3.000	Asbestos	PCME	EMSL	12/26/07	< 0.00082	No	No	
ASBESTOS-ST16-12/25/07	030739789-0011	East Face - North end at corner (scaffolding level)	12/25/07	1	2.990	Asbestos	PCME	EMSL	12/26/07	< 0.00083	No	No	
ASBESTOS-ST17-12/25/07	030739789-0012	North Face - West end at corner (scaffolding level)	12/25/07	1	3.050	Asbestos	PCME	EMSL	12/26/07	< 0.00081	No	No	

Note:

- Asbestos sample at Station 17 (North Face - West end at corner [scaffolding level]) on December 23, 2007 was not available for analysis on account of power failure.