

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
ASBESTOS-ST1-12/21/05	030538225-0001	Southwest Area (sidewalk bridge level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST2-12/21/05	030538225-0002	Southeast Area (sidewalk bridge level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST4-12/21/05	030538225-0003	Northwest Area (street-level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST5-12/21/05	030538225-0004	Firehouse #10 (roof level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST10-12/21/05	030538225-0005	North Side Sidewalk Bridge	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST100-12/21/05	030538225-0013	Station 10 Field Duplicate	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST11-12/21/05	030538225-0006	90 Trinity Place (roof level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST12-12/21/05	030538225-0007	110 Greenwich Street (roof level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST13-12/21/05	030538225-0008	Marriott Hotel, 38th Floor (roof level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST14-12/21/05	030538225-0009	West Face - South end at corner (scaffolding level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST15-12/21/05	030538225-0010	South Face - East end at corner (scaffolding level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST16-12/21/05	030538225-0011	East Face - North end at corner (scaffolding level)	12/21/05	1	3.020	Asbestos	PCME	EMSL	12/23/05	< 0.00082	No	No	
ASBESTOS-ST17-12/21/05	030538225-0012	North Face - West end at corner (scaffolding level)	12/21/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST1-12/22/05	030538275-0001	Southwest Area (sidewalk bridge level)	12/22/05	1	2.890	Asbestos	PCME	EMSL	12/23/05	< 0.00085	No	No	
ASBESTOS-ST2-12/22/05	030538275-0002	Southeast Area (sidewalk bridge level)	12/22/05	1	3.000	Asbestos	PCME	EMSL	12/23/05	< 0.00082	No	No	
ASBESTOS-ST4-12/22/05	030538275-0003	Northwest Area (street-level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST5-12/22/05	030538275-0004	Firehouse #10 (roof level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST10-12/22/05	030538275-0005	North Side Sidewalk Bridge	12/22/05	1	3.000	Asbestos	PCME	EMSL	12/23/05	< 0.00082	No	No	
ASBESTOS-ST11-12/22/05	030538275-0006	90 Trinity Place (roof level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST12-12/22/05	030538275-0007	110 Greenwich Street (roof level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST13-12/22/05	030538275-0008	Marriott Hotel, 38th Floor (roof level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST14-12/22/05	030538275-0009	West Face - South end at corner (scaffolding level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST15-12/22/05	030538275-0010	South Face - East end at corner (scaffolding level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	
ASBESTOS-ST16-12/22/05	030538275-0011	East Face - North end at corner (scaffolding level)	12/22/05	1	2.780	Asbestos	PCME	EMSL	12/23/05	< 0.00089	No	No	
ASBESTOS-ST17-12/22/05	030538275-0012	North Face - West end at corner (scaffolding level)	12/22/05	1	2.970	Asbestos	PCME	EMSL	12/23/05	< 0.00083	No	No	