

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-12/22/06	030641406-0001	Southwest Area (sidewalk bridge level)	12/22/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST2-12/22/06	030641406-0002	Southeast Area (sidewalk bridge level)	12/22/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST4-12/22/06	030641406-0003	Northwest Area (street-level)	12/22/06	1	3.030	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST5-12/22/06	030641406-0004	Firehouse #10 (roof level)	12/22/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST10-12/22/06	030641406-0005	North Side Sidewalk Bridge	12/22/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST11-12/22/06	030641406-0006	90 Trinity Place (roof level)	12/22/06	1	3.090	Asbestos	PCME	EMSL	12/26/06	< 0.00080	No	No	
ASBESTOS-ST12-12/22/06	030641406-0007	110 Greenwich Street (roof level)	12/22/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST13-12/22/06	030641406-0008	Marriott Hotel, 38th Floor (roof level)	12/22/06	1	3.030	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST14-12/22/06	030641406-0009	West Face - South end at corner (scaffolding level)	12/22/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST15-12/22/06	030641406-0010	South Face - East end at corner (scaffolding level)	12/22/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST16-12/22/06	030641406-0011	East Face - North end at corner (scaffolding level)	12/22/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST17-12/22/06	030641406-0012	North Face - West end at corner (scaffolding level)	12/22/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST1-12/23/06	030641405-0001	Southwest Area (sidewalk bridge level)	12/23/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST2-12/23/06	030641405-0002	Southeast Area (sidewalk bridge level)	12/23/06	1	3.030	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST4-12/23/06	030641405-0003	Northwest Area (street-level)	12/23/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST5-12/23/06	030641405-0004	Firehouse #10 (roof level)	12/23/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST10-12/23/06	030641405-0005	North Side Sidewalk Bridge	12/23/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST11-12/23/06	030641405-0006	90 Trinity Place (roof level)	12/23/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST12-12/23/06	030641405-0007	110 Greenwich Street (roof level)	12/23/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST13-12/23/06	030641405-0008	Marriott Hotel, 38th Floor (roof level)	12/23/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST14-12/23/06	030641405-0009	West Face - South end at corner (scaffolding level)	12/23/06	1	3.030	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST15-12/23/06	030641405-0010	South Face - East end at corner (scaffolding level)	12/23/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST16-12/23/06	030641405-0011	East Face - North end at corner (scaffolding level)	12/23/06	1	3.030	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST17-12/23/06	030641405-0012	North Face - West end at corner (scaffolding level)	12/23/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST1-12/24/06	030641407-0001	Southwest Area (sidewalk bridge level)	12/24/06	1	3.030	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST2-12/24/06	030641407-0002	Southeast Area (sidewalk bridge level)	12/24/06	1	3.020	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST4-12/24/06	030641407-0003	Northwest Area (street-level)	12/24/06	1	2.940	Asbestos	PCME	EMSL	12/27/06	< 0.00084	No	No	
ASBESTOS-ST5-12/24/06	030641407-0004	Firehouse #10 (roof level)	12/24/06	1	3.030	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST10-12/24/06	030641407-0005	North Side Sidewalk Bridge	12/24/06	1	3.000	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST11-12/24/06	030641407-0006	90 Trinity Place (roof level)	12/24/06	1	3.020	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST12-12/24/06	030641407-0007	110 Greenwich Street (roof level)	12/24/06	1	3.020	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST13-12/24/06	030641407-0008	Marriott Hotel, 38th Floor (roof level)	12/24/06	1	3.040	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST14-12/24/06	030641407-0009	West Face - South end at corner (scaffolding level)	12/24/06	1	3.020	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST15-12/24/06	030641407-0010	South Face - East end at corner (scaffolding level)	12/24/06	1	3.020	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST16-12/24/06	030641407-0011	East Face - North end at corner (scaffolding level)	12/24/06	1	3.030	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST17-12/24/06	030641407-0012	North Face - West end at corner (scaffolding level)	12/24/06	1	3.020	Asbestos	PCME	EMSL	12/27/06	< 0.00082	No	No	
ASBESTOS-ST1-12/25/06	030641408-0001	Southwest Area (sidewalk bridge level)	12/25/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST2-12/25/06	030641408-0002	Southeast Area (sidewalk bridge level)	12/25/06	1	3.050	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST5-12/25/06	030641408-0003	Firehouse #10 (roof level)	12/25/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST10-12/25/06	030641408-0004	North Side Sidewalk Bridge	12/25/06	1	3.060	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST11-12/25/06	030641408-0005	90 Trinity Place (roof level)	12/25/06	1	3.030	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST12-12/25/06	030641408-0006	110 Greenwich Street (roof level)	12/25/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST13-12/25/06	030641408-0007	Marriott Hotel, 38th Floor (roof level)	12/25/06	1	2.940	Asbestos	PCME	EMSL	12/26/06	< 0.00084	No	No	
ASBESTOS-ST14-12/25/06	030641408-0008	West Face - South end at corner (scaffolding level)	12/25/06	1	3.040	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST15-12/25/06	030641408-0009	South Face - East end at corner (scaffolding level)	12/25/06	1	3.020	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST16-12/25/06	030641408-0010	East Face - North end at corner (scaffolding level)	12/25/06	1	3.010	Asbestos	PCME	EMSL	12/26/06	< 0.00082	No	No	
ASBESTOS-ST17-12/25/06	030641408-0011	North Face - West end at corner (scaffolding level)	12/25/06	1	3.060	Asbestos	PCME	EMSL	12/26/06	< 0.00081	No	No	
ASBESTOS-ST1-12/26/06	030641522-0001	Southwest Area (sidewalk bridge level)	12/26/06	1	3.070	Asbestos	PCME	EMSL	12/27/06	< 0.00080	No	No	
ASBESTOS-ST2-12/26/06	030641522-0002	Southeast Area (sidewalk bridge level)	12/26/06	1	3.140	Asbestos	PCME	EMSL	12/27/06	< 0.00079	No	No	
ASBESTOS-ST4-12/26/06	030641522-0003	Northwest Area (street-level)	12/26/06	1	3.070	Asbestos	PCME	EMSL	12/27/06	< 0.00080	No	No	
ASBESTOS-ST5-12/26/06	030641522-0004	Firehouse #10 (roof level)	12/26/06	1	2.850	Asbestos	PCME	EMSL	12/27/06	< 0.00087	No	No	
ASBESTOS-ST10-12/26/06	030641522-0005	North Side Sidewalk Bridge	12/26/06	1	3.070	Asbestos	PCME	EMSL	12/27/06	< 0.00080	No	No	
ASBESTOS-ST11-12/26/06	030641522-0006	90 Trinity Place (roof level)	12/26/06	1	2.900	Asbestos	PCME	EMSL	12/27/06	< 0.00085	No	No	
ASBESTOS-ST12-12/26/06	030641522-0007	110 Greenwich Street (roof level)	12/26/06	1	3.060	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST13-12/26/06	030641522-0008	Marriott Hotel, 38th Floor (roof level)	12/26/06	1	2.920	Asbestos	PCME	EMSL	12/27/06	< 0.00085	No	No	
ASBESTOS-ST14-12/26/06	030641522-0009	West Face - South end at corner (scaffolding level)	12/26/06	1	3.060	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST15-12/26/06	030641522-0010	South Face - East end at corner (scaffolding level)	12/26/06	1	3.040	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST16-12/26/06	030641522-0011	East Face - North end at corner (scaffolding level)	12/26/06	1	3.030	Asbestos	PCME	EMSL	12/27/06	< 0.00081	No	No	
ASBESTOS-ST17-12/26/06	030641522-0012	North Face - West end at corner (scaffolding level)	12/26/06	1	2.900	Asbestos	PCME	EMSL	12/27/06	< 0.00085	No	No	

Note:

- Asbestos sample at Station 4 (Northwest Area [street-level]) on December 25, 2006 was not available for analysis on account of pump failure.