

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM10-ST1-1/11/2008	Southwest Area (sidewalk bridge level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST2-1/11/2008	Southeast Area (sidewalk bridge level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST4-1/11/2008	Northwest Area (street-level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST10-1/11/2008	North Side Sidewalk Bridge	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST100-1/11/2008	Station 10 Field Duplicate	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST11-1/11/2008	90 Trinity Place (roof level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST12-1/11/2008	110 Greenwich Street (roof level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-1/11/2008	Marriott Hotel, 38th Floor (roof level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-1/11/2008	West Face - South end at corner (scaffolding level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST15-1/11/2008	South Face - East end at corner (scaffolding level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST16-1/11/2008	East Face - North end at corner (scaffolding level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST17-1/11/2008	North Face - West end at corner (scaffolding level)	1/11/08	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST1-1/12/2008	Southwest Area (sidewalk bridge level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-1/12/2008	Southeast Area (sidewalk bridge level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST4-1/12/2008	Northwest Area (street-level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST5-1/12/2008	Firehouse #10 (roof level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST10-1/12/2008	North Side Sidewalk Bridge	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST100-1/12/2008	Station 10 Field Duplicate	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-1/12/2008	90 Trinity Place (roof level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-1/12/2008	110 Greenwich Street (roof level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-1/12/2008	Marriott Hotel, 38th Floor (roof level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST14-1/12/2008	West Face - South end at corner (scaffolding level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST15-1/12/2008	South Face - East end at corner (scaffolding level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-1/12/2008	East Face - North end at corner (scaffolding level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-1/12/2008	North Face - West end at corner (scaffolding level)	1/12/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-1/13/2008	Southwest Area (sidewalk bridge level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-1/13/2008	Southeast Area (sidewalk bridge level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-1/13/2008	Northwest Area (street-level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST5-1/13/2008	Firehouse #10 (roof level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST10-1/13/2008	North Side Sidewalk Bridge	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST100-1/13/2008	Station 10 Field Duplicate	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST11-1/13/2008	90 Trinity Place (roof level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST12-1/13/2008	110 Greenwich Street (roof level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-1/13/2008	Marriott Hotel, 38th Floor (roof level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-1/13/2008	West Face - South end at corner (scaffolding level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-1/13/2008	South Face - East end at corner (scaffolding level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST16-1/13/2008	East Face - North end at corner (scaffolding level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST17-1/13/2008	North Face - West end at corner (scaffolding level)	1/13/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	

Note:

1. The PM 10 reading at Station 5 (Firehouse #10 [roof level]) on January 11, 2008 was not available on account of instrument malfunction.