PM10-ST2-1/12/2007 S PM10-ST4-1/12/2007 N PM10-ST5-1/12/2007 Fit PM10-ST10-1/12/2007 N	EPA Southwest Area (sidewalk bridge level) Southeast Area (sidewalk bridge level) Northwest Area (street-level) Firehouse #10 (roof level) North Side Sidewalk Bridge	Target Air Quality Level A Site Specific Trigger L 1/12/07 1/12/07 1/12/07 1/12/07 1/12/07 1/12/07	evels 1440 1440	Particulate	Direct Deed		150 150	Air Quality Levels	Site Specific Trigger Levels	Comments		
PM10-ST2-1/12/2007 S PM10-ST4-1/12/2007 N PM10-ST5-1/12/2007 Fit PM10-ST10-1/12/2007 N	Southwest Area (sidewalk bridge level) Southeast Area (sidewalk bridge level) Northwest Area (street-level) Firehouse #10 (roof level) North Side Sidewalk Bridge	1/12/07 1/12/07 1/12/07	1440 1440		Diss at Data d		150					
PM10-ST2-1/12/2007 S PM10-ST4-1/12/2007 N PM10-ST5-1/12/2007 Fit PM10-ST10-1/12/2007 N	Southeast Area (sidewalk bridge level) Northwest Area (street-level) Firehouse #10 (roof level) North Side Sidewalk Bridge	1/12/07 1/12/07	1440		Discret Dans!	EPA Site Specific Trigger Levels						
PM10-ST4-1/12/2007 N PM10-ST5-1/12/2007 Fi PM10-ST10-1/12/2007 N	Northwest Area (street-level) Firehouse #10 (roof level) North Side Sidewalk Bridge	1/12/07			Direct Read	Met One E-BAM	20	No	No			
PM10-ST5-1/12/2007 Fi PM10-ST10-1/12/2007 N	Firehouse #10 (roof level)			Particulate	Direct Read	Met One E-BAM	15	No	No			
PM10-ST10-1/12/2007 N	North Side Sidewalk Bridge	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No			
	0		1440	Particulate	Direct Read	Met One E-BAM	23	No	No			
PM10-ST100-1/12/2007 S		1/12/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No			
	Station 10 Field Duplicate	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No			
PM10-ST11-1/12/2007 90	00 Trinity Place (roof level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No			
	10 Greenwich Street (roof level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No			
PM10-ST13-1/12/2007 M	Aarriott Hotel, 38th Floor (roof level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No			
PM10-ST14-1/12/2007 W	Vest Face - South end at corner (scaffolding level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No			
PM10-ST15-1/12/2007 S	South Face - East end at corner (scaffolding level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No			
	East Face - North end at corner (scaffolding level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No			
PM10-ST17-1/12/2007 N	North Face - West end at corner (scaffolding level)	1/12/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No			
PM10-ST1-1/13/2007 S	Southwest Area (sidewalk bridge level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	44	No	No			
PM10-ST2-1/13/2007 S	Southeast Area (sidewalk bridge level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No			
PM10-ST4-1/13/2007 N	Northwest Area (street-level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	43	No	No			
PM10-ST5-1/13/2007 Fi	Firehouse #10 (roof level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No			
PM10-ST10-1/13/2007 N	North Side Sidewalk Bridge	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	37	No	No			
PM10-ST100-1/13/2007 S	Station 10 Field Duplicate	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	33	No	No			
PM10-ST11-1/13/2007 90	0 Trinity Place (roof level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No			
PM10-ST12-1/13/2007 11	10 Greenwich Street (roof level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No			
PM10-ST13-1/13/2007 M	Aarriott Hotel, 38th Floor (roof level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No			
PM10-ST14-1/13/2007 W	Vest Face - South end at corner (scaffolding level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	37	No	No			
PM10-ST15-1/13/2007 S	South Face - East end at corner (scaffolding level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No			
PM10-ST16-1/13/2007 E	East Face - North end at corner (scaffolding level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No			
	North Face - West end at corner (scaffolding level)	1/13/07	1440	Particulate	Direct Read	Met One E-BAM	37	No	No			
PM10-ST1-1/14/2007 S	Southwest Area (sidewalk bridge level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No			
PM10-ST2-1/14/2007 S	Southeast Area (sidewalk bridge level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No			
PM10-ST4-1/14/2007 N	Northwest Area (street-level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No			
PM10-ST5-1/14/2007 Fi	irehouse #10 (roof level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No			
PM10-ST10-1/14/2007 N	North Side Sidewalk Bridge	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	37	No	No			
	Station 10 Field Duplicate	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	37	No	No			
	0 Trinity Place (roof level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	50	No	No			
	10 Greenwich Street (roof level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	22	No	No			
	Aarriott Hotel, 38th Floor (roof level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	49	No	No			
	Vest Face - South end at corner (scaffolding level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No			
	East Face - North end at corner (scaffolding level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No			
	North Face - West end at corner (scaffolding level)	1/14/07	1440	Particulate	Direct Read	Met One E-BAM	43	No	No			

Note: 1. PM 10 reading at Station 15 (South Face - East end at corner [scaffolding level]) on January 14, 2007 was not available on account of instrument malfunction.