

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-2/4/2009	Southwest Area (sidewalk bridge level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST2-2/4/2009	Southeast Area (sidewalk bridge level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-2/4/2009	Northwest Area (street-level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST5-2/4/2009	Firehouse #10 (roof level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-2/4/2009	North Side Sidewalk Bridge	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST100-2/4/2009	Station 10 Field Duplicate	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST11-2/4/2009	90 Trinity Place (roof level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-2/4/2009	110 Greenwich Street (roof level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-2/4/2009	Marriott Hotel, 38th Floor (roof level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-2/4/2009	West Face - South end at corner (scaffolding level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-2/4/2009	South Face - East end at corner (scaffolding level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-2/4/2009	North Face - West end at corner (scaffolding level)	2/4/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-2/5/2009	Southwest Area (sidewalk bridge level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-2/5/2009	Southeast Area (sidewalk bridge level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST4-2/5/2009	Northwest Area (street-level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-2/5/2009	Firehouse #10 (roof level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST10-2/5/2009	North Side Sidewalk Bridge	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST100-2/5/2009	Station 10 Field Duplicate	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST11-2/5/2009	90 Trinity Place (roof level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST12-2/5/2009	110 Greenwich Street (roof level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-2/5/2009	Marriott Hotel, 38th Floor (roof level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-2/5/2009	West Face - South end at corner (scaffolding level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-2/5/2009	South Face - East end at corner (scaffolding level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-2/5/2009	East Face - North end at corner (scaffolding level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-2/5/2009	North Face - West end at corner (scaffolding level)	2/5/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	

Note:

1. The PM10 reading from Station 16 (East Face - North end at corner [scaffolding level]) on February 4, 2009 was not available on account of instrument malfunction.