TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-2/5/2007	Southwest Area (sidewalk bridge level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST2-2/5/2007	Southeast Area (sidewalk bridge level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST4-2/5/2007	Northwest Area (street-level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST10-2/5/2007	North Side Sidewalk Bridge	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-2/5/2007	Station 10 Field Duplicate	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-2/5/2007	90 Trinity Place (roof level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST12-2/5/2007	110 Greenwich Street (roof level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-2/5/2007	Marriott Hotel, 38th Floor (roof level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-2/5/2007	West Face - South end at corner (scaffolding level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-2/5/2007	South Face - East end at corner (scaffolding level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-2/5/2007	East Face - North end at corner (scaffolding level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-2/5/2007	North Face - West end at corner (scaffolding level)	2/5/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-2/6/2007	Southwest Area (sidewalk bridge level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-2/6/2007	Southeast Area (sidewalk bridge level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-2/6/2007	North Side Sidewalk Bridge	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST100-2/6/2007	Station 10 Field Duplicate	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST11-2/6/2007	90 Trinity Place (roof level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-2/6/2007	110 Greenwich Street (roof level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST13-2/6/2007	Marriott Hotel, 38th Floor (roof level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-2/6/2007	West Face - South end at corner (scaffolding level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-2/6/2007	South Face - East end at corner (scaffolding level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST16-2/6/2007	East Face - North end at corner (scaffolding level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST17-2/6/2007	North Face - West end at corner (scaffolding level)	2/6/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	

- The PM 10 readings at Station 5 (Firehouse #10 [roof level]) on February 5 and 6, 2007 were not available on account of instrument malfunction.
 The PM 10 reading at Station 4 (Northwest Area [street-level]) on February 6, 2007 was not available on account of instrument malfunction.