TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	1
PM10-ST1-2/28/2007	Southwest Area (sidewalk bridge level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST2-2/28/2007	Southeast Area (sidewalk bridge level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-2/28/2007	Firehouse #10 (roof level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST10-2/28/2007	North Side Sidewalk Bridge	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-2/28/2007	Station 10 Field Duplicate	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-2/28/2007	90 Trinity Place (roof level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-2/28/2007	110 Greenwich Street (roof level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-2/28/2007	Marriott Hotel, 38th Floor (roof level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-2/28/2007	West Face - South end at corner (scaffolding level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST15-2/28/2007	South Face - East end at corner (scaffolding level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-2/28/2007	East Face - North end at corner (scaffolding level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST17-2/28/2007	North Face - West end at corner (scaffolding level)	2/28/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-3/1/2007	Southwest Area (sidewalk bridge level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST2-3/1/2007	Southeast Area (sidewalk bridge level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST5-3/1/2007	Firehouse #10 (roof level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST10-3/1/2007	North Side Sidewalk Bridge	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST100-3/1/2007	Station 10 Field Duplicate	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST11-3/1/2007	90 Trinity Place (roof level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST12-3/1/2007	110 Greenwich Street (roof level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST13-3/1/2007	Marriott Hotel, 38th Floor (roof level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST14-3/1/2007	West Face - South end at corner (scaffolding level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST15-3/1/2007	South Face - East end at corner (scaffolding level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-3/1/2007	East Face - North end at corner (scaffolding level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST17-3/1/2007	North Face - West end at corner (scaffolding level)	3/1/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	

Note:

1. The PM 10 readings at Station 4 (Northwest Area [street-level]) on February 28, 2007 and March 1, 2007 were not available on account of instrument malfunction.