

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-3/12/2008	Southwest Area (sidewalk bridge level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST2-3/12/2008	Southeast Area (sidewalk bridge level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST4-3/12/2008	Northwest Area (street-level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST10-3/12/2008	North Side Sidewalk Bridge	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-3/12/2008	Station 10 Field Duplicate	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST11-3/12/2008	90 Trinity Place (roof level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-3/12/2008	110 Greenwich Street (roof level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST13-3/12/2008	Marriott Hotel, 38th Floor (roof level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST14-3/12/2008	West Face - South end at corner (scaffolding level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST15-3/12/2008	South Face - East end at corner (scaffolding level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST16-3/12/2008	East Face - North end at corner (scaffolding level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST17-3/12/2008	North Face - West end at corner (scaffolding level)	3/12/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-3/13/2008	Southwest Area (sidewalk bridge level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST2-3/13/2008	Southeast Area (sidewalk bridge level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST4-3/13/2008	Northwest Area (street-level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST10-3/13/2008	North Side Sidewalk Bridge	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST100-3/13/2008	Station 10 Field Duplicate	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST11-3/13/2008	90 Trinity Place (roof level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST12-3/13/2008	110 Greenwich Street (roof level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-3/13/2008	Marriott Hotel, 38th Floor (roof level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST14-3/13/2008	West Face - South end at corner (scaffolding level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST15-3/13/2008	South Face - East end at corner (scaffolding level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST16-3/13/2008	East Face - North end at corner (scaffolding level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST17-3/13/2008	North Face - West end at corner (scaffolding level)	3/13/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	

Note:

1. The PM 10 readings at Station 5 (Firehouse #10 [roof level]) on March 12 and 13, 2008 were not available on account of instrument malfunction.