

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-3/14/2007	Southwest Area (sidewalk bridge level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST2-3/14/2007	Southeast Area (sidewalk bridge level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST4-3/14/2007	Northwest Area (street-level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST5-3/14/2007	Firehouse #10 (roof level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST10-3/14/2007	North Side Sidewalk Bridge	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST100-3/14/2007	Station 10 Field Duplicate	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST11-3/14/2007	90 Trinity Place (roof level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST12-3/14/2007	110 Greenwich Street (roof level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST13-3/14/2007	Marriott Hotel, 38th Floor (roof level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST15-3/14/2007	South Face - East end at corner (scaffolding level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST16-3/14/2007	East Face - North end at corner (scaffolding level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST17-3/14/2007	North Face - West end at corner (scaffolding level)	3/14/07	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST1-3/15/2007	Southwest Area (sidewalk bridge level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST2-3/15/2007	Southeast Area (sidewalk bridge level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST4-3/15/2007	Northwest Area (street-level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST5-3/15/2007	Firehouse #10 (roof level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST10-3/15/2007	North Side Sidewalk Bridge	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST100-3/15/2007	Station 10 Field Duplicate	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST11-3/15/2007	90 Trinity Place (roof level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST12-3/15/2007	110 Greenwich Street (roof level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST13-3/15/2007	Marriott Hotel, 38th Floor (roof level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST14-3/15/2007	West Face - South end at corner (scaffolding level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST15-3/15/2007	South Face - East end at corner (scaffolding level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-3/15/2007	East Face - North end at corner (scaffolding level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST17-3/15/2007	North Face - West end at corner (scaffolding level)	3/15/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	

Note:

1. The PM 10 reading at Station 14 (West Face - South end at corner [scaffolding level]) on March 14, 2007 was not available on account of instrument malfunction.