TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	1
PM10-ST1-3/17/2008	Southwest Area (sidewalk bridge level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-3/17/2008	Southeast Area (sidewalk bridge level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST4-3/17/2008	Northwest Area (street-level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST5-3/17/2008	Firehouse #10 (roof level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST10-3/17/2008	North Side Sidewalk Bridge	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST100-3/17/2008	Station 10 Field Duplicate	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST11-3/17/2008	90 Trinity Place (roof level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-3/17/2008	110 Greenwich Street (roof level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-3/17/2008	Marriott Hotel, 38th Floor (roof level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST15-3/17/2008	South Face - East end at corner (scaffolding level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-3/17/2008	East Face - North end at corner (scaffolding level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST17-3/17/2008	North Face - West end at corner (scaffolding level)	3/17/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST1-3/18/2008	Southwest Area (sidewalk bridge level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST2-3/18/2008	Southeast Area (sidewalk bridge level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST4-3/18/2008	Northwest Area (street-level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST5-3/18/2008	Firehouse #10 (roof level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST10-3/18/2008	North Side Sidewalk Bridge	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST100-3/18/2008	Station 10 Field Duplicate	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST11-3/18/2008	90 Trinity Place (roof level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST12-3/18/2008	110 Greenwich Street (roof level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-3/18/2008	Marriott Hotel, 38th Floor (roof level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST14-3/18/2008	West Face - South end at corner (scaffolding level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST15-3/18/2008	South Face - East end at corner (scaffolding level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST16-3/18/2008	East Face - North end at corner (scaffolding level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-3/18/2008	North Face - West end at corner (scaffolding level)	3/18/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	

Note:
1. The PM 10 reading at Station 14 (West Face - South end at corner [scaffolding level]) on March 17, 2008 was not available on account of instrument malfunction.