

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-4/1/2009	Southwest Area (sidewalk bridge level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST2-4/1/2009	Southeast Area (sidewalk bridge level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST4-4/1/2009	Northwest Area (street-level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST5-4/1/2009	Firehouse #10 (roof level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST10-4/1/2009	North Side Sidewalk Bridge	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	50	No	No	
PM10-ST100-4/1/2009	Station 10 Field Duplicate	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST11-4/1/2009	90 Trinity Place (roof level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-4/1/2009	110 Greenwich Street (roof level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST13-4/1/2009	Marriott Hotel, 38th Floor (roof level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST14-4/1/2009	West Face - South end at corner (scaffolding level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST15-4/1/2009	South Face - East end at corner (scaffolding level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST16-4/1/2009	East Face - North end at corner (scaffolding level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST17-4/1/2009	North Face - West end at corner (scaffolding level)	4/1/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST2-4/2/2009	Southeast Area (sidewalk bridge level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST4-4/2/2009	Northwest Area (street-level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST5-4/2/2009	Firehouse #10 (roof level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST10-4/2/2009	North Side Sidewalk Bridge	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST100-4/2/2009	Station 10 Field Duplicate	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST11-4/2/2009	90 Trinity Place (roof level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST12-4/2/2009	110 Greenwich Street (roof level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST13-4/2/2009	Marriott Hotel, 38th Floor (roof level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	40			
PM10-ST14-4/2/2009	West Face - South end at corner (scaffolding level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST15-4/2/2009	South Face - East end at corner (scaffolding level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST16-4/2/2009	East Face - North end at corner (scaffolding level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST17-4/2/2009	North Face - West end at corner (scaffolding level)	4/2/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	

Note:

1. The PM10 reading from Station 1 (Southwest Area [sidewalk bridge level]) on April 2, 2009 was not available on account of power failure.