

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-4/3/2006	Southwest Area (sidewalk bridge level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST2-4/3/2006	Southeast Area (sidewalk bridge level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST4-4/3/2006	Northwest Area (street-level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST5-4/3/2006	Firehouse #10 (roof level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST10-4/3/2006	North Side Sidewalk Bridge	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-4/3/2006	Station 10 Field Duplicate	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST11-4/3/2006	90 Trinity Place (roof level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST12-4/3/2006	110 Greenwich Street (roof level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST13-4/3/2006	Marriott Hotel, 38th Floor (roof level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST14-4/3/2006	West Face - South end at corner (scaffolding level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST15-4/3/2006	South Face - East end at corner (scaffolding level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-4/3/2006	East Face - North end at corner (scaffolding level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST17-4/3/2006	North Face - West end at corner (scaffolding level)	4/3/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST1-4/4/2006	Southwest Area (sidewalk bridge level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-4/4/2006	Southeast Area (sidewalk bridge level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST4-4/4/2006	Northwest Area (street-level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST5-4/4/2006	Firehouse #10 (roof level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-4/4/2006	North Side Sidewalk Bridge	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-4/4/2006	90 Trinity Place (roof level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-4/4/2006	110 Greenwich Street (roof level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-4/4/2006	Marriott Hotel, 38th Floor (roof level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST15-4/4/2006	South Face - East end at corner (scaffolding level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST16-4/4/2006	East Face - North end at corner (scaffolding level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST17-4/4/2006	North Face - West end at corner (scaffolding level)	4/4/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	

Notes:

1. The PM 10 readings at Station 14 (West Face - South end at corner [scaffolding level]) on April 4, 2006 were not available on account of a temporary power failure.
2. The PM 10 readings at Station 100 (Station 10 Field Duplicate) on April 4, 2006 were not available on account of pump failure.