

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM10-ST1-4/22/2009	Southwest Area (sidewalk bridge level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-4/22/2009	Southeast Area (sidewalk bridge level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST4-4/22/2009	Northwest Area (street-level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST5-4/22/2009	Firehouse #10 (roof level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST10-4/22/2009	North Side Sidewalk Bridge	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST100-4/22/2009	Station 10 Field Duplicate	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST11-4/22/2009	90 Trinity Place (roof level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST12-4/22/2009	110 Greenwich Street (roof level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST13-4/22/2009	Marriott Hotel, 38th Floor (roof level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST15-4/22/2009	South Face - East end at corner (scaffolding level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST16-4/22/2009	East Face - North end at corner (scaffolding level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST17-4/22/2009	North Face - West end at corner (scaffolding level)	4/22/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST1-4/23/2009	Southwest Area (sidewalk bridge level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST2-4/23/2009	Southeast Area (sidewalk bridge level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-4/23/2009	Northwest Area (street-level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST5-4/23/2009	Firehouse #10 (roof level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-4/23/2009	North Side Sidewalk Bridge	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST100-4/23/2009	Station 10 Field Duplicate	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST11-4/23/2009	90 Trinity Place (roof level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST12-4/23/2009	110 Greenwich Street (roof level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST13-4/23/2009	Marriott Hotel, 38th Floor (roof level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-4/23/2009	West Face - South end at corner (scaffolding level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST15-4/23/2009	South Face - East end at corner (scaffolding level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-4/23/2009	East Face - North end at corner (scaffolding level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST17-4/23/2009	North Face - West end at corner (scaffolding level)	4/23/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	

Note:

1. The PM10 reading from Station 14 (West Face - South end at corner [scaffolding level]) on April 22, 2009 was not available on account of instrument malfunction.