

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-5/19/2008	Southwest Area (sidewalk bridge level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST2-5/19/2008	Southeast Area (sidewalk bridge level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST4-5/19/2008	Northwest Area (street-level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST5-5/19/2008	Firehouse #10 (roof level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-5/19/2008	North Side Sidewalk Bridge	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST11-5/19/2008	90 Trinity Place (roof level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST12-5/19/2008	110 Greenwich Street (roof level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-5/19/2008	Marriott Hotel, 38th Floor (roof level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-5/19/2008	West Face - South end at corner (scaffolding level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST15-5/19/2008	South Face - East end at corner (scaffolding level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST16-5/19/2008	East Face - North end at corner (scaffolding level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-5/19/2008	North Face - West end at corner (scaffolding level)	5/19/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST1-5/20/2008	Southwest Area (sidewalk bridge level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST2-5/20/2008	Southeast Area (sidewalk bridge level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	57	No	No	
PM10-ST4-5/20/2008	Northwest Area (street-level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST5-5/20/2008	Firehouse #10 (roof level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST10-5/20/2008	North Side Sidewalk Bridge	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST11-5/20/2008	90 Trinity Place (roof level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST12-5/20/2008	110 Greenwich Street (roof level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST13-5/20/2008	Marriott Hotel, 38th Floor (roof level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST14-5/20/2008	West Face - South end at corner (scaffolding level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST15-5/20/2008	South Face - East end at corner (scaffolding level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST16-5/20/2008	East Face - North end at corner (scaffolding level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST17-5/20/2008	North Face - West end at corner (scaffolding level)	5/20/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	

Note:

1. The PM 10 readings at Station 100 (Station 10 Field Duplicate) on May 19 and 20, 2008 were not available on account of instrument malfunction.