TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-5/22/2006	Southwest Area (sidewalk bridge level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST2-5/22/2006	Southeast Area (sidewalk bridge level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST4-5/22/2006	Northwest Area (street-level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST5-5/22/2006	Firehouse #10 (roof level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST10-5/22/2006	North Side Sidewalk Bridge	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST100-5/22/2006	Station 10 Field Duplicate	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST12-5/22/2006	110 Greenwich Street (roof level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-5/22/2006	Marriott Hotel, 38th Floor (roof level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST14-5/22/2006	West Face - South end at corner (scaffolding level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-5/22/2006	South Face - East end at corner (scaffolding level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-5/22/2006	East Face - North end at corner (scaffolding level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-5/22/2006	North Face - West end at corner (scaffolding level)	5/22/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-5/23/2006	Southwest Area (sidewalk bridge level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-5/23/2006	Southeast Area (sidewalk bridge level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST4-5/23/2006	Northwest Area (street-level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST5-5/23/2006	Firehouse #10 (roof level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST10-5/23/2006	North Side Sidewalk Bridge	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST100-5/23/2006	Station 10 Field Duplicate	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST12-5/23/2006	110 Greenwich Street (roof level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-5/23/2006	Marriott Hotel, 38th Floor (roof level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST14-5/23/2006	West Face - South end at corner (scaffolding level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-5/23/2006	South Face - East end at corner (scaffolding level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST16-5/23/2006	East Face - North end at corner (scaffolding level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-5/23/2006	North Face - West end at corner (scaffolding level)	5/23/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	

Note: 1. The PM 10 readings at Station 11 (90 Trinity Place [roof level]) on May 22 and 23, 2006 were not available on account of instrument malfunction.