

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-6/19/2006	Southwest Area (sidewalk bridge level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	54	No	No	
PM10-ST2-6/19/2006	Southeast Area (sidewalk bridge level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	63	No	No	
PM10-ST4-6/19/2006	Northwest Area (street-level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	60	No	No	
PM10-ST5-6/19/2006	Firehouse #10 (roof level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	56	No	No	
PM10-ST10-6/19/2006	North Side Sidewalk Bridge	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	64	No	No	
PM10-ST11-6/19/2006	90 Trinity Place (roof level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST12-6/19/2006	110 Greenwich Street (roof level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	55	No	No	
PM10-ST13-6/19/2006	Marriott Hotel, 38th Floor (roof level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST14-6/19/2006	West Face - South end at corner (scaffolding level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST15-6/19/2006	South Face - East end at corner (scaffolding level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST16-6/19/2006	East Face - North end at corner (scaffolding level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST17-6/19/2006	North Face - West end at corner (scaffolding level)	6/19/06	1440	Particulate	Direct Read	Met One E-BAM	61	No	No	
PM10-ST1-6/20/2006	Southwest Area (sidewalk bridge level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST2-6/20/2006	Southeast Area (sidewalk bridge level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST4-6/20/2006	Northwest Area (street-level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST5-6/20/2006	Firehouse #10 (roof level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST10-6/20/2006	North Side Sidewalk Bridge	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST100-6/20/2006	Station 10 Field Duplicate	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST11-6/20/2006	90 Trinity Place (roof level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST12-6/20/2006	110 Greenwich Street (roof level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST13-6/20/2006	Marriott Hotel, 38th Floor (roof level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST14-6/20/2006	West Face - South end at corner (scaffolding level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST15-6/20/2006	South Face - East end at corner (scaffolding level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST16-6/20/2006	East Face - North end at corner (scaffolding level)	6/20/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	

Notes:

1. The PM 10 readings at Station 100 (Station 10 Field Duplicate) on June 19, 2006 were not available on account of instrument malfunction.
2. The PM 10 readings at Station 17 (North Face - West end at corner [scaffolding level]) on June 20, 2006 were not available on account of instrument malfunction.