

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-7/24/2009	Southwest Area (sidewalk bridge level)	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST2-7/24/2009	Southeast Area (sidewalk bridge level)	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST4-7/24/2009	Northwest Area (street-level)	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-7/24/2009	Firehouse #10 (roof level)	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST10-7/24/2009	North Side Sidewalk Bridge	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-7/24/2009	Station 10 Field Duplicate	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-7/24/2009	110 Greenwich Street (roof level)	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST13-7/24/2009	Marriott Hotel, 38th Floor (roof level)	7/24/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST1-7/25/2009	Southwest Area (sidewalk bridge level)	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-7/25/2009	Southeast Area (sidewalk bridge level)	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST4-7/25/2009	Northwest Area (street-level)	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST5-7/25/2009	Firehouse #10 (roof level)	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST10-7/25/2009	North Side Sidewalk Bridge	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST100-7/25/2009	Station 10 Field Duplicate	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST12-7/25/2009	110 Greenwich Street (roof level)	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST13-7/25/2009	Marriott Hotel, 38th Floor (roof level)	7/25/09	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST1-7/26/2009	Southwest Area (sidewalk bridge level)	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST2-7/26/2009	Southeast Area (sidewalk bridge level)	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST4-7/26/2009	Northwest Area (street-level)	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST5-7/26/2009	Firehouse #10 (roof level)	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST10-7/26/2009	North Side Sidewalk Bridge	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST100-7/26/2009	Station 10 Field Duplicate	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-7/26/2009	110 Greenwich Street (roof level)	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST13-7/26/2009	Marriott Hotel, 38th Floor (roof level)	7/26/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	

Note:

1. The PM10 readings from Station 11 (90 Trinity Place [roof level]) on July 24, 25, and 26, 2009 were not available on account of instrument malfunction.