

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-9/26/2007	Southwest Area (sidewalk bridge level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST2-9/26/2007	Southeast Area (sidewalk bridge level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	56	No	No	
PM10-ST4-9/26/2007	Northwest Area (street-level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST5-9/26/2007	Firehouse #10 (roof level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST10-9/26/2007	North Side Sidewalk Bridge	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	60	No	No	
PM10-ST100-9/26/2007	Station 10 Field Duplicate	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST12-9/26/2007	110 Greenwich Street (roof level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST13-9/26/2007	Marriott Hotel, 38th Floor (roof level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST14-9/26/2007	West Face - South end at corner (scaffolding level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST15-9/26/2007	South Face - East end at corner (scaffolding level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	50	No	No	
PM10-ST16-9/26/2007	East Face - North end at corner (scaffolding level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST17-9/26/2007	North Face - West end at corner (scaffolding level)	9/26/07	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST1-9/27/2007	Southwest Area (sidewalk bridge level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST2-9/27/2007	Southeast Area (sidewalk bridge level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	65	No	No	
PM10-ST5-9/27/2007	Firehouse #10 (roof level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST10-9/27/2007	North Side Sidewalk Bridge	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST100-9/27/2007	Station 10 Field Duplicate	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-9/27/2007	90 Trinity Place (roof level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST12-9/27/2007	110 Greenwich Street (roof level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST13-9/27/2007	Marriott Hotel, 38th Floor (roof level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST14-9/27/2007	West Face - South end at corner (scaffolding level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST15-9/27/2007	South Face - East end at corner (scaffolding level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST16-9/27/2007	East Face - North end at corner (scaffolding level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST17-9/27/2007	North Face - West end at corner (scaffolding level)	9/27/07	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	

Note:

1. The PM 10 reading at Station 11 (90 Trinity Place [roof level]) on September 26, 2007 was not available on account of instrument malfunction.
2. The PM 10 reading at Station 4 (Northwest Area [street-level]) on September 27, 2007 was not available on account of instrument malfunction.