

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-10/2/2006	Southwest Area (sidewalk bridge level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST2-10/2/2006	Southeast Area (sidewalk bridge level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-10/2/2006	Northwest Area (street-level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST5-10/2/2006	Firehouse #10 (roof level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-10/2/2006	North Side Sidewalk Bridge	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST100-10/2/2006	Station 10 Field Duplicate	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-10/2/2006	90 Trinity Place (roof level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-10/2/2006	110 Greenwich Street (roof level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST13-10/2/2006	Marriott Hotel, 38th Floor (roof level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-10/2/2006	West Face - South end at corner (scaffolding level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-10/2/2006	South Face - East end at corner (scaffolding level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST16-10/2/2006	East Face - North end at corner (scaffolding level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST17-10/2/2006	North Face - West end at corner (scaffolding level)	10/2/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST2-10/3/2006	Southeast Area (sidewalk bridge level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST4-10/3/2006	Northwest Area (street-level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-10/3/2006	Firehouse #10 (roof level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST10-10/3/2006	North Side Sidewalk Bridge	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST100-10/3/2006	Station 10 Field Duplicate	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST11-10/3/2006	90 Trinity Place (roof level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST12-10/3/2006	110 Greenwich Street (roof level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST13-10/3/2006	Marriott Hotel, 38th Floor (roof level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST14-10/3/2006	West Face - South end at corner (scaffolding level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST15-10/3/2006	South Face - East end at corner (scaffolding level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST16-10/3/2006	East Face - North end at corner (scaffolding level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST17-10/3/2006	North Face - West end at corner (scaffolding level)	10/3/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	

Notes:

- PM 10 reading at Station 1 (Southwest Area [sidewalk bridge level]) on October 3, 2006 was not available on account of instrument malfunction.