

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-10/15/2007	Southwest Area (sidewalk bridge level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST4-10/15/2007	Northwest Area (street-level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST5-10/15/2007	Firehouse #10 (roof level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST10-10/15/2007	North Side Sidewalk Bridge	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-10/15/2007	Station 10 Field Duplicate	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST11-10/15/2007	90 Trinity Place (roof level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-10/15/2007	110 Greenwich Street (roof level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-10/15/2007	Marriott Hotel, 38th Floor (roof level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-10/15/2007	West Face - South end at corner (scaffolding level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST15-10/15/2007	South Face - East end at corner (scaffolding level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST16-10/15/2007	East Face - North end at corner (scaffolding level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-10/15/2007	North Face - West end at corner (scaffolding level)	10/15/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-10/16/2007	Southwest Area (sidewalk bridge level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-10/16/2007	Northwest Area (street-level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST5-10/16/2007	Firehouse #10 (roof level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-10/16/2007	North Side Sidewalk Bridge	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST100-10/16/2007	Station 10 Field Duplicate	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST11-10/16/2007	90 Trinity Place (roof level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST12-10/16/2007	110 Greenwich Street (roof level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-10/16/2007	Marriott Hotel, 38th Floor (roof level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST14-10/16/2007	West Face - South end at corner (scaffolding level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST15-10/16/2007	South Face - East end at corner (scaffolding level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST16-10/16/2007	East Face - North end at corner (scaffolding level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST17-10/16/2007	North Face - West end at corner (scaffolding level)	10/16/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	

Note:

1. The PM 10 readings at Station 2 (Southeast Area [sidewalk bridge level]) on October 15 and October 16, 2007 were not available on account of instrument malfunction.