

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-11/3/2008	Southwest Area (sidewalk bridge level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST2-11/3/2008	Southeast Area (sidewalk bridge level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST4-11/3/2008	Northwest Area (street-level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-11/3/2008	Firehouse #10 (roof level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-11/3/2008	North Side Sidewalk Bridge	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-11/3/2008	Station 10 Field Duplicate	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST11-11/3/2008	90 Trinity Place (roof level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST13-11/3/2008	Marriott Hotel, 38th Floor (roof level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST14-11/3/2008	West Face - South end at corner (scaffolding level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST15-11/3/2008	South Face - East end at corner (scaffolding level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST16-11/3/2008	East Face - North end at corner (scaffolding level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST17-11/3/2008	North Face - West end at corner (scaffolding level)	11/3/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST1-11/4/2008	Southwest Area (sidewalk bridge level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST2-11/4/2008	Southeast Area (sidewalk bridge level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST4-11/4/2008	Northwest Area (street-level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST5-11/4/2008	Firehouse #10 (roof level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST10-11/4/2008	North Side Sidewalk Bridge	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST100-11/4/2008	Station 10 Field Duplicate	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST11-11/4/2008	90 Trinity Place (roof level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST12-11/4/2008	110 Greenwich Street (roof level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST13-11/4/2008	Marriott Hotel, 38th Floor (roof level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST14-11/4/2008	West Face - South end at corner (scaffolding level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST15-11/4/2008	South Face - East end at corner (scaffolding level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST16-11/4/2008	East Face - North end at corner (scaffolding level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST17-11/4/2008	North Face - West end at corner (scaffolding level)	11/4/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	

Note:

1. The PM 10 reading at Station 12 (110 Greenwich Street [roof level]) on November 3, 2008 was not available on account of instrument malfunction.