

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-12/30/2009	Southwest Area (sidewalk bridge level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-12/30/2009	Southeast Area (sidewalk bridge level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST4-12/30/2009	Northwest Area (street-level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST5-12/30/2009	Firehouse #10 (roof level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST10-12/30/2009	North Side Sidewalk Bridge	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST100-12/30/2009	Station 10 Field Duplicate	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST11-12/30/2009	90 Trinity Place (roof level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST12-12/30/2009	110 Greenwich Street (roof level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-12/30/2009	Marriott Hotel, 38th Floor (roof level)	12/30/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-12/31/2009	Southwest Area (sidewalk bridge level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST2-12/31/2009	Southeast Area (sidewalk bridge level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST4-12/31/2009	Northwest Area (street-level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST5-12/31/2009	Firehouse #10 (roof level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST10-12/31/2009	North Side Sidewalk Bridge	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST100-12/31/2009	Station 10 Field Duplicate	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST11-12/31/2009	90 Trinity Place (roof level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST12-12/31/2009	110 Greenwich Street (roof level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST13-12/31/2009	Marriott Hotel, 38th Floor (roof level)	12/31/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST1-1/2/2010	Southwest Area (sidewalk bridge level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-1/2/2010	Southeast Area (sidewalk bridge level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-1/2/2010	Northwest Area (street-level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST5-1/2/2010	Firehouse #10 (roof level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST10-1/2/2010	North Side Sidewalk Bridge	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST100-1/2/2010	Station 10 Field Duplicate	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-1/2/2010	90 Trinity Place (roof level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST12-1/2/2010	110 Greenwich Street (roof level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-1/2/2010	Marriott Hotel, 38th Floor (roof level)	1/2/10	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

1. The PM10 readings are not available for January 1, and 3, 2010 since no sampling was conducted on these days due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.