

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-2/11/2008	Southwest Area (sidewalk bridge level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST2-2/11/2008	Southeast Area (sidewalk bridge level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST4-2/11/2008	Northwest Area (street-level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST10-2/11/2008	North Side Sidewalk Bridge	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST100-2/11/2008	Station 10 Field Duplicate	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST11-2/11/2008	90 Trinity Place (roof level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST12-2/11/2008	110 Greenwich Street (roof level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST13-2/11/2008	Marriott Hotel, 38th Floor (roof level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST14-2/11/2008	West Face - South end at corner (scaffolding level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST15-2/11/2008	South Face - East end at corner (scaffolding level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST16-2/11/2008	East Face - North end at corner (scaffolding level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST17-2/11/2008	North Face - West end at corner (scaffolding level)	2/11/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST1-2/12/2008	Southwest Area (sidewalk bridge level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST2-2/12/2008	Southeast Area (sidewalk bridge level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST4-2/12/2008	Northwest Area (street-level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST10-2/12/2008	North Side Sidewalk Bridge	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST100-2/12/2008	Station 10 Field Duplicate	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST11-2/12/2008	90 Trinity Place (roof level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST12-2/12/2008	110 Greenwich Street (roof level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST13-2/12/2008	Marriott Hotel, 38th Floor (roof level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST14-2/12/2008	West Face - South end at corner (scaffolding level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST15-2/12/2008	South Face - East end at corner (scaffolding level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST16-2/12/2008	East Face - North end at corner (scaffolding level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST17-2/12/2008	North Face - West end at corner (scaffolding level)	2/12/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	

Note:

1. The PM 2.5 readings at Station 5 (Firehouse #10 [roof level]) on February 11 and 12, 2008 were not available on account of instrument malfunction.