

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-3/3/2006	Southwest Area (sidewalk bridge level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST2-3/3/2006	Southeast Area (sidewalk bridge level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST4-3/3/2006	Northwest Area (street-level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST5-3/3/2006	Firehouse #10 (roof level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST10-3/3/2006	North Side Sidewalk Bridge	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST100-3/3/2006	Station 10 Field Duplicate	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST11-3/3/2006	90 Trinity Place (roof level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST12-3/3/2006	110 Greenwich Street (roof level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST13-3/3/2006	Marriott Hotel, 38th Floor (roof level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST14-3/3/2006	West Face - South end at corner (scaffolding level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST15-3/3/2006	South Face - East end at corner (scaffolding level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST16-3/3/2006	East Face - North end at corner (scaffolding level)	3/3/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST1-3/4/2006	Southwest Area (sidewalk bridge level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST2-3/4/2006	Southeast Area (sidewalk bridge level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST4-3/4/2006	Northwest Area (street-level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST5-3/4/2006	Firehouse #10 (roof level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST10-3/4/2006	North Side Sidewalk Bridge	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST100-3/4/2006	Station 10 Field Duplicate	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST11-3/4/2006	90 Trinity Place (roof level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST12-3/4/2006	110 Greenwich Street (roof level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST13-3/4/2006	Marriott Hotel, 38th Floor (roof level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST14-3/4/2006	West Face - South end at corner (scaffolding level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST15-3/4/2006	South Face - East end at corner (scaffolding level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST16-3/4/2006	East Face - North end at corner (scaffolding level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST17-3/4/2006	North Face - West end at corner (scaffolding level)	3/4/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST1-3/5/2006	Southwest Area (sidewalk bridge level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-3/5/2006	Southeast Area (sidewalk bridge level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST4-3/5/2006	Northwest Area (street-level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST5-3/5/2006	Firehouse #10 (roof level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST10-3/5/2006	North Side Sidewalk Bridge	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST100-3/5/2006	Station 10 Field Duplicate	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	3	No	No	
PM2.5-ST11-3/5/2006	90 Trinity Place (roof level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	3	No	No	
PM2.5-ST12-3/5/2006	110 Greenwich Street (roof level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST13-3/5/2006	Marriott Hotel, 38th Floor (roof level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST14-3/5/2006	West Face - South end at corner (scaffolding level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST15-3/5/2006	South Face - East end at corner (scaffolding level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST16-3/5/2006	East Face - North end at corner (scaffolding level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST17-3/5/2006	North Face - West end at corner (scaffolding level)	3/5/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	

Note:

1. The PM 2.5 reading at Station 17 (North Face - West end at corner [scaffolding level]) on March 3, 2006 was not available on account of instrument malfunction.