

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM2.5-ST1-4/6/2009	Southwest Area (sidewalk bridge level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST2-4/6/2009	Southeast Area (sidewalk bridge level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST4-4/6/2009	Northwest Area (street-level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM2.5-ST5-4/6/2009	Firehouse #10 (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST10-4/6/2009	North Side Sidewalk Bridge	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST100-4/6/2009	Station 10 Field Duplicate	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST11-4/6/2009	90 Trinity Place (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST12-4/6/2009	110 Greenwich Street (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM2.5-ST13-4/6/2009	Marriott Hotel, 38th Floor (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST14-4/6/2009	West Face - South end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST15-4/6/2009	South Face - East end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST16-4/6/2009	East Face - North end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST1-4/7/2009	Southwest Area (sidewalk bridge level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST2-4/7/2009	Southeast Area (sidewalk bridge level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST4-4/7/2009	Northwest Area (street-level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST5-4/7/2009	Firehouse #10 (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST10-4/7/2009	North Side Sidewalk Bridge	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST100-4/7/2009	Station 10 Field Duplicate	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST11-4/7/2009	90 Trinity Place (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST12-4/7/2009	110 Greenwich Street (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST13-4/7/2009	Marriott Hotel, 38th Floor (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST14-4/7/2009	West Face - South end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST15-4/7/2009	South Face - East end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST16-4/7/2009	East Face - North end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST17-4/7/2009	North Face - West end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	

Note:

1. The PM2.5 reading from Station 17 (North Face - West end at corner [scaffolding level]) on April 6, 2009 was not available on account of instrument malfunction.