

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-6/5/2009	Southwest Area (sidewalk bridge level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST2-6/5/2009	Southeast Area (sidewalk bridge level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST4-6/5/2009	Northwest Area (street-level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST5-6/5/2009	Firehouse #10 (roof level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST10-6/5/2009	North Side Sidewalk Bridge	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST100-6/5/2009	Station 10 Field Duplicate	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST11-6/5/2009	90 Trinity Place (roof level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST12-6/5/2009	110 Greenwich Street (roof level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-6/5/2009	Marriott Hotel, 38th Floor (roof level)	6/5/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST1-6/6/2009	Southwest Area (sidewalk bridge level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST2-6/6/2009	Southeast Area (sidewalk bridge level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST4-6/6/2009	Northwest Area (street-level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST5-6/6/2009	Firehouse #10 (roof level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-6/6/2009	North Side Sidewalk Bridge	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST100-6/6/2009	Station 10 Field Duplicate	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-6/6/2009	90 Trinity Place (roof level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST12-6/6/2009	110 Greenwich Street (roof level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST13-6/6/2009	Marriott Hotel, 38th Floor (roof level)	6/6/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST1-6/7/2009	Southwest Area (sidewalk bridge level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST2-6/7/2009	Southeast Area (sidewalk bridge level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST4-6/7/2009	Northwest Area (street-level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST5-6/7/2009	Firehouse #10 (roof level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST10-6/7/2009	North Side Sidewalk Bridge	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST100-6/7/2009	Station 10 Field Duplicate	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST11-6/7/2009	90 Trinity Place (roof level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST12-6/7/2009	110 Greenwich Street (roof level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST13-6/7/2009	Marriott Hotel, 38th Floor (roof level)	6/7/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	