

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>40</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>65</b>			
PM2.5-ST1-8/13/2008	Southwest Area (sidewalk bridge level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST2-8/13/2008	Southeast Area (sidewalk bridge level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST4-8/13/2008	Northwest Area (street-level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-8/13/2008	North Side Sidewalk Bridge	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST100-8/13/2008	Station 10 Field Duplicate	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST11-8/13/2008	90 Trinity Place (roof level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST12-8/13/2008	110 Greenwich Street (roof level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST13-8/13/2008	Marriott Hotel, 38th Floor (roof level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST14-8/13/2008	West Face - South end at corner (scaffolding level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST15-8/13/2008	South Face - East end at corner (scaffolding level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST17-8/13/2008	North Face - West end at corner (scaffolding level)	8/13/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST1-8/14/2008	Southwest Area (sidewalk bridge level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST2-8/14/2008	Southeast Area (sidewalk bridge level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST4-8/14/2008	Northwest Area (street-level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST10-8/14/2008	North Side Sidewalk Bridge	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST100-8/14/2008	Station 10 Field Duplicate	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST11-8/14/2008	90 Trinity Place (roof level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST12-8/14/2008	110 Greenwich Street (roof level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST13-8/14/2008	Marriott Hotel, 38th Floor (roof level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST14-8/14/2008	West Face - South end at corner (scaffolding level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST15-8/14/2008	South Face - East end at corner (scaffolding level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST17-8/14/2008	North Face - West end at corner (scaffolding level)	8/14/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	

- Note:
1. The PM 2.5 readings at Station 5 (Firehouse #10 [roof level]) on August 13 and 14, 2008 were not available on account of instrument malfunction.
  2. The PM 2.5 readings at Station 16 (East Face - North end at corner [scaffolding level]) on August 13 and 14, 2008 were not available on account of instrument malfunction.