

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
PM2.5-ST1-11/14/2008	Southwest Area (sidewalk bridge level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST2-11/14/2008	Southeast Area (sidewalk bridge level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST4-11/14/2008	Northwest Area (street-level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST5-11/14/2008	Firehouse #10 (roof level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST10-11/14/2008	North Side Sidewalk Bridge	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST100-11/14/2008	Station 10 Field Duplicate	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST11-11/14/2008	90 Trinity Place (roof level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST12-11/14/2008	110 Greenwich Street (roof level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST13-11/14/2008	Marriott Hotel, 38th Floor (roof level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST14-11/14/2008	West Face - South end at corner (scaffolding level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST15-11/14/2008	South Face - East end at corner (scaffolding level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST17-11/14/2008	North Face - West end at corner (scaffolding level)	11/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST1-11/15/2008	Southwest Area (sidewalk bridge level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST2-11/15/2008	Southeast Area (sidewalk bridge level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST4-11/15/2008	Northwest Area (street-level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST5-11/15/2008	Firehouse #10 (roof level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST10-11/15/2008	North Side Sidewalk Bridge	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST100-11/15/2008	Station 10 Field Duplicate	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST11-11/15/2008	90 Trinity Place (roof level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST12-11/15/2008	110 Greenwich Street (roof level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST13-11/15/2008	Marriott Hotel, 38th Floor (roof level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST14-11/15/2008	West Face - South end at corner (scaffolding level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST15-11/15/2008	South Face - East end at corner (scaffolding level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST17-11/15/2008	North Face - West end at corner (scaffolding level)	11/15/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST1-11/16/2008	Southwest Area (sidewalk bridge level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST2-11/16/2008	Southeast Area (sidewalk bridge level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST4-11/16/2008	Northwest Area (street-level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST5-11/16/2008	Firehouse #10 (roof level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST10-11/16/2008	North Side Sidewalk Bridge	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST100-11/16/2008	Station 10 Field Duplicate	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST11-11/16/2008	90 Trinity Place (roof level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST12-11/16/2008	110 Greenwich Street (roof level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST13-11/16/2008	Marriott Hotel, 38th Floor (roof level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST14-11/16/2008	West Face - South end at corner (scaffolding level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST15-11/16/2008	South Face - East end at corner (scaffolding level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST17-11/16/2008	North Face - West end at corner (scaffolding level)	11/16/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	

Note:
1. The PM2.5 readings at Station 16 (East Face - North end at corner [scaffolding level]) on November 14, 15 and 16, 2008 were not available on account of instrument malfunction.