

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST2-11/15/2006	Southeast Area (sidewalk bridge level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST4-11/15/2006	Northwest Area (street-level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM2.5-ST5-11/15/2006	Firehouse #10 (roof level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST10-11/15/2006	North Side Sidewalk Bridge	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-11/15/2006	90 Trinity Place (roof level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST13-11/15/2006	Marriott Hotel, 38th Floor (roof level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST14-11/15/2006	West Face - South end at corner (scaffolding level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST15-11/15/2006	South Face - East end at corner (scaffolding level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST16-11/15/2006	East Face - North end at corner (scaffolding level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM2.5-ST17-11/15/2006	North Face - West end at corner (scaffolding level)	11/15/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST1-11/16/2006	Southwest Area (sidewalk bridge level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST2-11/16/2006	Southeast Area (sidewalk bridge level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST4-11/16/2006	Northwest Area (street-level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST5-11/16/2006	Firehouse #10 (roof level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST11-11/16/2006	90 Trinity Place (roof level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST12-11/16/2006	110 Greenwich Street (roof level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST13-11/16/2006	Marriott Hotel, 38th Floor (roof level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST14-11/16/2006	West Face - South end at corner (scaffolding level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST16-11/16/2006	East Face - North end at corner (scaffolding level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST17-11/16/2006	North Face - West end at corner (scaffolding level)	11/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	

Note:

1. PM 2.5 readings at Station 1 (Southwest Area [sidewalk bridge level]), Station 100 (Station 10 Field Duplicate), and Station 12 (110 Greenwich Street [roof level]) on November 15, 2006 were not available on account of instrument malfunction.
2. PM 2.5 readings at Station 10 (North Side Sidewalk Bridge), Station 100 (Station 10 Field Duplicate), and Station 15 (South Face - East end at corner [scaffolding level]) on November 16, 2006 were not available on account of instrument malfunction.