

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-1/2/08	030800121-0001	Southwest Area (sidewalk bridge level)	1/2/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST2-1/2/08	030800121-0002	Southeast Area (sidewalk bridge level)	1/2/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST4-1/2/08	030800121-0003	Northwest Area (street-level)	1/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST5-1/2/08	030800121-0004	Firehouse #10 (roof level)	1/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST10-1/2/08	030800121-0005	North Side Sidewalk Bridge	1/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST11-1/2/08	030800121-0006	90 Trinity Place (roof level)	1/2/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST12-1/2/08	030800121-0007	110 Greenwich Street (roof level)	1/2/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST13-1/2/08	030800121-0008	Marriott Hotel, 38th Floor (roof level)	1/2/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST14-1/2/08	030800121-0009	West Face - South end at corner (scaffolding level)	1/2/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST15-1/2/08	030800121-0010	South Face - East end at corner (scaffolding level)	1/2/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST16-1/2/08	030800121-0011	East Face - North end at corner (scaffolding level)	1/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST17-1/2/08	030800121-0012	North Face - West end at corner (scaffolding level)	1/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/08	< 13.00	No	No	
ASBESTOS-ST1-1/3/08	030800230-0001	Southwest Area (sidewalk bridge level)	1/3/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST2-1/3/08	030800230-0002	Southeast Area (sidewalk bridge level)	1/3/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST4-1/3/08	030800230-0003	Northwest Area (street-level)	1/3/08	1	2.760	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST5-1/3/08	030800230-0004	Firehouse #10 (roof level)	1/3/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST10-1/3/08	030800230-0005	North Side Sidewalk Bridge	1/3/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST11-1/3/08	030800230-0006	90 Trinity Place (roof level)	1/3/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST12-1/3/08	030800230-0007	110 Greenwich Street (roof level)	1/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST13-1/3/08	030800230-0008	Marriott Hotel, 38th Floor (roof level)	1/3/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST14-1/3/08	030800230-0009	West Face - South end at corner (scaffolding level)	1/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST15-1/3/08	030800230-0010	South Face - East end at corner (scaffolding level)	1/3/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST16-1/3/08	030800230-0011	East Face - North end at corner (scaffolding level)	1/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	
ASBESTOS-ST17-1/3/08	030800230-0012	North Face - West end at corner (scaffolding level)	1/3/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/4/08	< 13.00	No	No	